
OBIS: Remote Powered – Laser not Emitting

Situation: Customer has the Remote powered up and switched ON, but the laser is not emitting a beam and remains in STANDBY mode.



Here are some recommended generators:



Agilent 81110A



Rigol DG4162



Tektronix AFG 3000 Series



Tektronix AWG 5000 Series



Tektronix AWG 7000 Series