
## How to use Logger.exe



The Logger.exe can be found in Start - Visuallasermarker – tools – Logger.

To Start the Logger.exe VMC, VLM and LCP has to be closed. In case one of theses programs is active the Logger.exe will not start.

Logger - Mic... 

AlVLMProje... 

Symincys - [D:... 

Wichtige Inf... 

Re: MCT Err... 

Acrobat Re... 

Q:()PodlechC 


D:()

Document1 ...

In case of an Error just press Save Error button and all Log files and Screenshots will be saved.

All logfiles will be saved in your Visuallasermarker\logging directory for each pressing of Save Error a Directory will be created with all Logging information available the name of the directory is the time and date of the Error.

In the Options additional Files can be selected which will be saved in the Error Case.




Files have to be typed in with full path information and to log several Files separate them with ";"


Like shown in that example which will save 2 additional files.



## Some Logging mechanisms need to be activated first.

1. PCLD Trace must be activated in the Registry






The registry key "Trace PCLD ON/OFF" must be set to 1


## 2. VMC\_HK logging

In the options of the VMC\_HK activate Trace to File (VMC\_HK.log) And activate Full Status List Info



## 3. Comspy

Is not needed to be activated this will done automatically by the Tool but before using it the first time the Options should be set correctly.



Make sure that the important Traces are activated.

When using the Logger.exe the Filename and File Path are not important since it is automatically saved in the right directory.

When using the Comspy manually make sure the path exists otherwise the file cant be saved.