

## XENON AUTO ASSESSORS & VALUERS LTD.

Head Office: Pan Africa House, 1st Floor; Along Moi Avenue; P.O. Box 365(80100), Msa. Phone: 0725 777195, 0700 799054 ⊠info@xenonassessors.co.ke www.xenonassessors.co.ke

## Nairobi Branch:

Embassy House. 1st Floor, Along Harambee Avenue; Phone: 0710 420234, 0725 777195

## **Eldoret Branch:**

Watergate Plaza 3rd Floor, Along Ronald Ngala Road. **Phone**: 0719 494235, 0725 777195, 0700 799054

**DATE: 11th MAY, 2021** 

Mombasa · Nairobi · Eldoret · Nakuru · Meru · Kitui

THE CLAIMS MANAGER,

**MUA INSURANCE CO. LTD,** 

P.O. BOX 30129-00100,

NAIROBI.

**INSURED:** CHINA STATE CONSTRUCTION ENGINEERING

**CLAIM NO:** 223/21/MK/HO

OUR REF; XA/04-21/MUA/NRB-0120/2021

<u>SUPPLEMENTARY REPORT FOR M.V. REG. NO. KCW 024S, A TOYOTA RAV 4, DBA-ACA36W, STATION</u> WAGON.

Our Assessment Report dated 19<sup>™</sup> April 2021,

The repairer called our offices informing that a damaged part had not been awarded

We revisited the accident vehicle and inspected areas of concern and noted that above sentiments were true and consistent with the accident.


We kindly urge you to allow for the replacement of the same as per below supplementary estimate;

	Supplementary Estimate	<u>Kshs.</u>
1	R.H.S Wiper Arm with cap Holder	5,000.00
1	R.H.S Wiper Blade	1,500.00
		<u>6,500.00</u>
	Sub- Total	6,500.00
	Add 16% vat	<u>1,040.00</u>
	Supplementary Net Total	<u>7,540.00</u>

NB - Part price were quoted From the open market sources. – Nairobi.

- 16%vat not factored because its OWN repairs.

These developments will adjust upwards Estimated Total Cost of Repairs from **Kshs**. **405**,**500**.**00** to **Kshs**.**412**,**000**.**00**.



## We remain obliged to serve









Yours Faithfully,

Kennedy K. Kyalo, **PRINCIPAL OFFICER**