

Prime Accident Assessors Ltd.

Motor Loss Assessors, Adjusters & Valuers

Sami Centre Embakasi, 2nd Floor - Along Eastern By Pass Opposite G.S.U Training College; P.O. Box 2786 – 00200, Nairobi.

Tel: 0722 832720; 0777 832 720 Email: primeasltd@gmail.com / primeaa@yahoo.com,

ASSESSMENT REPORT

OUR REF. DATE

PAA/558/SANLAM/2021 30-Jul-2021, Fri

ASSIGNMENT DETAILS

INSURER SANLAM GENERAL INSURANC	E	INSURED CHINA RAILWAY NO.10 ENGINEERING CO LTD			
CLAIM NO. POLICY NO TBA			SUM INSURED		
INSTRUCTIONS BY CHRISTINE MASAWA	INSTRUCTIONS DATE 29-Jul-2021, Thu		GARAGED AT KARMEC CO LTD		TRANSPORT MODE TOWED

VEHICLE PARTICULARS

REG NO			VEHICLE MAKE JMC			MODEL NO. VIGUS			BODY TYPE D.CAB PICK-UP
YEAR 2017	1	HASSIS NO. ENGINE NO. JX4024			ENGINE CC 2,400cc.	FUEL TYPE COLOUR WHITE			
MILEA	MILEAGE INSPECTED AT KARMEC CO LTD		DATE OF INS 30-Jul-202		NOTES				

SURVEY OBSERVATIONS

MECHANICAL CONDITION											
IGNITION Not Tested		ENGINE Not Tested	CHASS Okay	SIS SUSPENSION STEER Not Tested Not Te				TRANSMISSION Not Tested			
	BRA	KING	TYRES (TREADS RATING)								
FOOTBRAKE Serviceable		HANDBRAKE Holding	RHF 10%	LHF 10%	RHR 10%	LHR 10%					
LIGHTS »		HEADLIGHTS BROKEN	BRAKI Okay	ING / H	AZARD	LIGHT				FOG LIGHTS Not Applicable	
WINDSCREEN Okay		WINDOWS BROKEN	DOOR Okay	LOCKS					AC SY		SRS SYSTEM Not Tested
RADIO SYSTEM NOT TESTED		DASH FASCIA & INS	TRUMEI	NTS	EXTER Okay	*			· · · · · · · · · · · · · · · · · · ·	UPHOLSTERY	
	COMPINED MODERATE LIFE END IMPACT COURT ED WITH MODERATE BUS OF ANCING IMPACT										

NATURE OF IMPACT COMBINED MODERATE LHF END IMPACT COUPLED WITH MODERATE RHS GLANCING IMPACT



Photo showing damage caused by the impact

PRE-ACCIDENT VALUE	Kshs. 3,700,000.00
ESTIMATED COST OF REPAIRS	Kshs. 413,304.46
SALVAGE VALUE	
REPAIRER	KARMEC CO LTD
REPAIRER CONTACT PERSON / MOBILE	MATHEW
REPAIR AUTHORITY STATUS	Authorized Pending

	GENERAL SUMMARY									
RECOM	IMENDED CLAIM SETTL	EMENT METHOD								
● A	Authorise Repairs Settle as cash in lieu Pay out pre-accident value									
PRE-A	PRE-ACCIDENT DAMAGES NOTED									
	NOT ESTABLISHED									
DAMAG	SED PARTS									
то ве	REPLACED	See repairs estimate bel	ow							
то ве	REPAIRED	LHF DOOR, RHR DOOR	R, BONN	IET LID						
то ве	REPAINTED	FRONT BUMPER, RHR	DOOR,	BONNE	T LID, LI	HF WING, L	HF DOOR			
		REI	PAIRS	ESTIM	ATE					
#		Particulars			Qty.	Unit Pr	ice		Amount	
1.	FRONT BUMPER ASSI	EMBLY			1	61	,637.93		61,637.93	
2.	LHS HEADLIGHT				1				30,603.45	
3.	LHS FOG COVER				1	5,	5,000.00 5,00			
4.	LHF BUMMPER SLIDE	Ĭ.			1	5	5,086.21 5,08			
5.	5. LHF WING					33	33,620.69 33,62			
6.	RHS SIDE MIRROR				1	22,413.79 22,4			22,413.79	
7.	RHF DOOR GLASS				1	7	7,327.69 7,32			
8.	FRONT GRILLE				1	11,206.90			11,206.90	
9.	LHF WHEEL ARC MOL	DING			1	23,833.33			23,833.33	
10.	LHF WING LINER				1	6	,465.52		6,465.52	
11.	WASHER BOTTLE				1	7,327.59			7,327.59	
						Su	btotal		214,523.10	
			Les	s 5% Di	iscount	10),726.16		203,796.95	
[Oper	Market Parts]						,			
1.	LABOUR				1	76,	00.00		76,000.00	
2.	2. PAINTING					68,000.00			68,000.00	
3.	MISCELLANEOUS				1	8,	500.00		8,500.00	
						Su	btotal		152,500.00	
	I	tem	Qty	Unit	Price	Contrib. %	Contribu	tion	Net Amount	
1.	1. 1									
					Gros	s Cost of R	epairs	_	356,296.95	
				Add 16	% VAT	57	,007.51		413,304.46	
	413,304.46									

SPECIAL NOTES TO REPAIRER

- 1. The repair estimate is limited to work rendered necessary as a direct result of an accident.
- 2. Should any latent damage be noticed during repairs, the assessors must be notified immediately.
- 3. Any vehicle under repairs following assessment should not be released to the insured / owner without the express authority of the insurer.
- 4. Vehicles once repaired must be re-inspected before release.
- 5. All parts removed for replacement must be kept under safe custody of the repairer until collected / inspected by insurer.

REPAIRER COMMITMENT

We commit to carry out repairs on the vehicle as per the procudure described under REPAIR INSTRUCTIONS and at the cost outlined under REPAIRS ESTIMATE


KARMEC CO LTD		
NOMINATED REPAIRER	OWNER / AUTHORISED PERSON [NAME & SIGNATURE]	OFFICIAL STAMP

PROJECTED REPAIRS DURATION: 2 Weeks

GEOFFREY M. KINYUA PRIME A. ASSESSORS LTD.













KARMEC COMPANY LIMITED P.O BOX 3257-00100,NAIROBI KENYA INDUSTRIAL PARK, MOMBASA ROAD ${\bf Email: karmeccompanyltd@gmail.com}$



Date 日期	July 28, 2021
Valid Until 有效期截止	August 11, 2021
Quote No. 单号	Mk/S02/2021/02
Customer ID 客户ID	

Quotation

报价单

			white Description 报例年			
CHINA RAI	LWAY NO.10 ENG GROUP CO. LTD	INEERING	REG: :KDD 086J I Nature of Work: :Accide		IGUS (white in color eading :1537KM)
Item 品名	Status 状态		KRA PIN :			
1	70tg		rt description 配件详情	Qty 数量	Unit price 单价	Total price 合计
2			Front bumper assy	1	61,637.93	61,637.9
3			Lhs headlight /	1	30,603.45	30,603.4
4			Fog light cover	1	5,000.00	5,000.0
5			Lhs bumper slide	1	5,086.21	5,086.2
6			ns mudguard (Wing)	1	33,620.69	33,620.6
7			Rhs side mirror	1	22,413.79	22,413.7
8			hs front door glass	1	7,327.69	7,327.6
9			mper grill complete	1	11,206.90	11,206.9
10		Lhs fr	ont wheel arc moulding	1	23,833.33	23,833.3
11			Lhs stone guard	1	6,465.52	
12			iper washer bottle	1	7,327.59	6,465.5
		Gas, p	anel beating & labour	1	85,000.00	7,327.5
13		Towin	g breakdown charges	1		85,000.0
14		Painti	ng materials & labour	1	50,000.00	¥50,000.0
15			Misc	1	75,000.00	75,000.00
					12,500.00	12,500.00
CHASE ORDI	ER WITH CASH/C	CHEQUE/PAT	YBILL		Subtotal 不含税	437,023.00
单时随附现金/支	票/M-pesa转账				Vat 16% 税金	69,923.69
ENTOPTIONS					Total 含視总价	506,946.78

A TILL NUMBER 965 520
T/T 以下为银行账号信息
name: KARMEC COMPANY LIMITED
number:USD 0810278639286
number: KSHS 0810278639277
e:Equity Bank (Kenya) Limited
nk Branch: Equity Centre Supreme Branch
: EQBLKENA
86
nber: 081
be collected in prior to provision of services/goods described in this

Prepaired by : Mathew Rotich



Prime Accident Assessors Ltd.

Motor Loss Assessors, Adjusters & Valuers

Sami Centre Embakasi, 2nd Floor - Along Eastern By Pass
Opposite G.S.U Training College; P.O. Box 2786 – 00200, Nairobi.
Tel: 0722 832720; 0777 832 720 Email: primeasltd@gmail.com / primeaa@yahoo.com,

FEE NOTE

DATE OUR REF FEE NOTE NO.

30-07-2021, Fri PAA/558/SANLAM/2021 23679

INSURER INSURANCE INSURED CHINA RAILWAY NO.10						NGINEERING CO LTD
REG. NO. KDD 086J	VEHICLE MAKE		CLAIM 010/08		54206/2021/07	POLICY NO. TBA
Survey Fee	N	QTY	UNITCO	OST	5,500.00	PRIME ACCIDENT HSSESSURS BOX:3878 NRB TEL:652290 PIN#PO51098270J VAT:0135384M VAT Dept VAT# PIN# 0000 01 KSH ZERO RATED 6380.00 B TOTAL 6380.00 CASH 6380.00 UAT ANALYSIS B=16.00% VAT B 880.00 012200 01 ITEMS 26-07-21 17:44 LEGAL RECEIPT KRA/ETR/10032006 004490 M/C # PT006511 FM # 00006511
			Subt	otal	5,500.00	
	Add 16%	6 VAT	880	.00	6,380.00	
			TO	TAL	Ksh. 6,380.00	
Note						