



Easy Stones - Seattle
6012 S 196th St
Kent, WA 98032

Packinglist# 145301
Date: 7/29/2026



printed on Sunday, August 02, 2026 06:36 pm

Packing List

Bill To:				Ship To:		
Creative Surfaces 9968 Padilla Heights RD Anacortes, WA 98221 United States P: 360-588-1463 E: CreativeSurfaces@outlook.com				Job Name: Creative Surfaces Creative Surfaces 9968 Padilla Heights RD Anacortes, WA 98221 United States		
Sales Rep	PO #	Payment Terms	SO#	Est. Ship Date	Weight	Prepared By
Krish		30 Days	145301	8/3/2026	0.00 LBS	Krish
Description				Quantity	Unit Price	Extended
Serial Num	Barcode	Bundle	Slab Number	Block	Location(Bin)	
Black Pearl Dual LF/POL 3cm (7)				508.06 SF		
14012-8	ES11103834	2/14012	08	SE1709	SEA	134" X 78" = 72.58 SF
14012-9	ES11103836	2/14012	09	SE1709	SEA	134" X 78" = 72.58 SF
14012-10	ES11103837	2/14012	10	SE1709	SEA	134" X 78" = 72.58 SF
14012-11	ES11103947	2/14012	11	SE1709	SEA	134" X 78" = 72.58 SF
14012-12	ES11103948	2/14012	12	SE1709	SEA	134" X 78" = 72.58 SF
14012-13	ES11103949	2/14012	13	SE1709	SEA	134" X 78" = 72.58 SF
14012-14	ES11103950	2/14012	14	SE1709	SEA	134" X 78" = 72.58 SF

Terms and Conditions:
Inspection Acknowledgement: Please preform a visual inspection of slabs received at time of receipt and again prior to cutting. For proper inspection remove any plastic covering and inspect materials for consistency in color within and between slabs, as well as with the specified sample. Additionally, check for defects in pattern and finish, and inspect for signs of cracking or pitting. If the slabs are deemed unsuitable for use, they can be exchanged prior to cutting or alteration. Please note that claims cannot be considered if the slab has been altered in any way. By signing this receipt, you acknowledge that you accept these conditions.
Quartz Fabrication Acknowledgement: Dust derived from the quartz slab fabrication can contain substances, such as crystalline silica, that may pose health risks. During the fabrication or removal process exposure to silica dust, particularly during cutting, grinding or demolition can result in health issues including acute lung injury, silicosis, or cancer. Ensure protection to exposure by wearing a respirator during these tasks. Utilize wet cutting methods and avoid dry cutting altogether. Persons with preexisting respiratory disorders may be more susceptible to adverse effects. For detailed information visit USA OSHA alert 29 CFR 1910.1053 at www.osha.gov/laws-regs/regulations/standardnumber/1910/1910.1053 and Proposition 65 warning issued by the state of California at www.P65Warnings.ca.gov in reference to crystalline silica. By signing this receipt, you acknowledge and understand these safety precautions and agree to communicate them to all applicable personnel within your company.
Terms: All returns without quality issues will be subject to a 15% restocking fee. Request for return must be submitted within two weeks of receipt. Invoices not paid by the due date are subject to an 1.5% monthly finance charge. The buyer will bear all costs associated with the collection of delinquent invoices, including attorney fees. Title to the products shall remain with the seller until full payment of the invoice is received. Credit Card payments are subject to a 3% processing fee.

Name: _____ Signature: _____ Date: _____