

Bench sample · Y branch

Full all-pairs plan · 21 pairs / 7 pins

Only isolated, disconnected wire-only passive assemblies. No mains, batteries, components or safety-critical use.

User-recorded results only. No measured evidence, electrical certification, thresholds, or hardware control.

Recording summary

Untested: 18 · User pass: 1 · User fail: 1 · Skipped: 1

Manual check record

Print this document using your browser. No links or scripts are required.

#	Pair A	Pair B	Expected	User record	Note
1	J1 / 1	J1 / 2	NOT CONNECTED	User pass	Synthetic observation
2	J1 / 1	J1 / 3	NOT CONNECTED	User fail	_____
3	J1 / 1	J2 / 1	CONNECTED	Skipped	_____
4	J1 / 1	J2 / 2	NOT CONNECTED	Untested	_____
5	J1 / 1	J3 / 1	CONNECTED	Untested	_____
6	J1 / 1	J3 / 2	NOT CONNECTED	Untested	_____
7	J1 / 2	J1 / 3	NOT CONNECTED	Untested	_____
8	J1 / 2	J2 / 1	NOT CONNECTED	Untested	_____
9	J1 / 2	J2 / 2	CONNECTED	Untested	_____
10	J1 / 2	J3 / 1	NOT CONNECTED	Untested	_____
11	J1 / 2	J3 / 2	CONNECTED	Untested	_____
12	J1 / 3	J2 / 1	NOT CONNECTED	Untested	_____
13	J1 / 3	J2 / 2	NOT CONNECTED	Untested	_____
14	J1 / 3	J3 / 1	NOT CONNECTED	Untested	_____
15	J1 / 3	J3 / 2	NOT CONNECTED	Untested	_____
16	J2 / 1	J2 / 2	NOT CONNECTED	Untested	_____
17	J2 / 1	J3 / 1	CONNECTED	Untested	_____
18	J2 / 1	J3 / 2	NOT CONNECTED	Untested	_____
19	J2 / 2	J3 / 1	NOT CONNECTED	Untested	_____
20	J2 / 2	J3 / 2	CONNECTED	Untested	_____
21	J3 / 1	J3 / 2	NOT CONNECTED	Untested	_____

Declared pins

PROBEPLAN / E2E6750B

Bench sample · Y branch

Pin reference · logical grouping, NOT connector face orientation

Only isolated, disconnected wire-only passive assemblies. No mains, batteries, components or safety-critical use.

User-recorded results only. No measured evidence, electrical certification, thresholds, or hardware control.

J1

Source end · labels only

PIN	Net
● 1	LINE_A
● 2	LINE_B
● 3	ISOLATED

J2

Branch A · labels only

PIN	Net
● 1	LINE_A
● 2	LINE_B

J3

Branch B · labels only

PIN	Net
● 1	LINE_A
● 2	LINE_B