

Bench A · decoding contract

Fields REGISTER MAP	5	Passing assertions SAVED EXPECTATIONS	5	Checks to resolve COVERAGE & REGRESSION	0	Overlapping addresses ALIASES NEED REVIEW	1
------------------------	---	--	---	--	---	--	---

A portable review record

ALL ASSERTIONS PASS

Save the JSON and Python verifier together. Run the same checks without a browser.

Snapshot / field	Status	Raw value / canonical bits	Actual value	Expected / tolerance
steady temperature	PASS	-25 FFE7	-2.5	-2.5 0
steady counter	PASS	100000 000186A0	100000	100000 0
steady counter_low	PASS	34464 86A0	34464	34464 0
steady flow	PASS	12.5 41480000	12.5	12.5 0
input status	PASS	7 0007	7	7 0

A pass means agreement with saved expectations. It does not establish that expectations are correct, cover unrecorded states, or certify device conformance or safe operation.