Document Number: MCUXSDKK24FRN Rev. 0, 03/2018

# MCUXpresso SDK Release Notes Supporting TWR-K24F120M

### 1 Overview

The MCUXpresso Software Development Kit (SDK) is a collection of software enablement for Microcontrollers that includes peripheral drivers, high-level stacks including USB and lwIP, integration with WolfSSL and mbed TLS cryptography libraries, other middleware packages, such as multicore support and FatFs, and integrated RTOS support for FreeRTOS<sup>TM</sup> OS. In addition to the base enablement, the MCUXpresso SDK is augmented with demo applications and driver example projects, and API documentation to help the customers quickly leverage the support of the MCUXpresso SDK.

For the latest version of this and other MCUXpresso SDK documents, see the MCUXpresso SDK homepage MCUXpresso-SDK: Software Development Kit.

#### **NOTE**

See the attached Change Logs section at the end of this document to reference the device-specific driver logs, middleware logs, and RTOS log.

#### **Contents**

I	Overview	l
2	MCUXpresso SDK	1
3	Development tools	2
4	Supported development systems	2
5	Release contents	2
6	MCUXpresso SDK release package	3
7	MISRA compliance	5
8	Known issues	6

# 2 MCUXpresso SDK



#### **Development tools**

As part of the MCUXpresso software and tools, MCUXpressoSDK is the evolution of Kinetis SDK v2.3.0, includes support for both LPC and i.MX System-on-Chips (SoC). The same drivers, APIs, and middleware are still available with support for Kinetis, LPC, and i.MX silicon. Easily import your SDK into the new MCUXpresso IDE toolchain to have access to all of the available components, examples, and demos for your target silicon. In addition to the MCUXpresso IDE, support for the MCUXpresso Config Tools allows for easy cloning of existing SDK examples and demos, allowing users to easily leverage the existing software examples provided by the SDK for their own projects.

#### NOTE

In order to maintain compatibility with legacy FSL code, the filenames and source code in MCUXpresso SDK containing the legacy Freescale prefix 'FSL' has been left as is. The 'FSL' prefix has been redefined as the NXP Foundation Software Library.

# 3 Development tools

The MCUXpresso SDK was compiled and tested with these development tools:

- Kinetis Design Studio IDE v3.2
- IAR Embedded Workbench for Arm version 8.22.1
- MDK-Arm Microcontroller Development Kit (Keil)<sup>®</sup> 5.23
- Makefiles support with GCC revision v6-2017-q2 from Arm Embedded
- MCUXpresso IDE v10.1.0

# 4 Supported development systems

This release supports boards and devices listed in this table. Boards and devices in boldface were tested in this release:

Table 1. Supported MCU devices and development boards

Development boards	MCU devices
	MK24FN256VDC12, MK24FN1M0VDC12, MK24FN1M0VLL12, MK24FN1M0VLQ12, MK24FN1M0CAJ12

### 5 Release contents

This table provides an overview of the MCUXpresso SDK release package contents and locations.

Table 2. Release contents

Deliverable	Location
Boards	<install_dir>/boards</install_dir>
Demo applications	<install_dir>/boards/<board_name>/demo_apps</board_name></install_dir>
USB demo applications	<install_dir>/boards/<board_name>/usb_examples</board_name></install_dir>
Driver examples	<install_dir>/boards/<board_name>/driver_examples</board_name></install_dir>

Table continues on the next page...

#### Table 2. Release contents (continued)

RTOS examples	<install_dir>/boards/<board_name>/rtos_examples</board_name></install_dir>
Documentation	<install_dir>/docs</install_dir>
USB Documentation	<install_dir>/docs/usb</install_dir>
Middleware	<install_dir>/middleware</install_dir>
DMA manager	<install_dir>/middleware/dma_manager</install_dir>
FatFs stack	<install_dir>/middleware/fatfs</install_dir>
SDMMC card driver	<install_dir>/middleware/sdmmc</install_dir>
USB stack	<install_dir>/middleware/usb</install_dir>
Driver, SoC header files, extension header files and feature header files, utilities	<install_dir>/devices/<device_name></device_name></install_dir>
Cortex Microcontroller Software Interface Standard (CMSIS) ARM Cortex®-M header files, DSP library source	<install_dir>/CMSIS</install_dir>
Peripheral Drivers	<install_dir>/devices/<device_name>/drivers</device_name></install_dir>
Utilities such as debug console	<install_dir>/devices/<device_name>/utilities</device_name></install_dir>
RTOS Kernel Code	<install_dir>/rtos</install_dir>
Tools	<install_dir>/tools</install_dir>

# 6 MCUXpresso SDK release package

The MCUXpresso SDK release package contents are aligned with the silicon subfamily it supports. This includes the boards, CMSIS, devices, documentation, middleware, and RTOS support.

## 6.1 Device support

The device folder contains all available software enablement for the specific System-on-Chip (SoC) subfamily. This folder includes clock-specific implementation, device register header file, device register feature header file, CMSIS derived device SVD, and the system configuration source files. Included with the standard SoC support are folders containing peripheral drivers, toolchain support, and a simple debug console.

The device-specific header files provide a direct access to the MCU peripheral registers. The device header file provides an overall SoC memory mapped register definition. In addition to the overall device memory mapped header file, the MCUXpresso SDK also includes the feature header file for each peripheral instantiated on the SoC.

The toolchain folder contains the startup code and linker files for each supported toolchain. The startup code is a CMSIS-compliant startup that efficiently transfers the code execution to the main() function.

# 6.1.1 Board support

The boards folder provides the board-specific demo applications, driver examples, RTOS, and middleware examples.

MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 03/2018

MCUXpresso SDK release package

## 6.1.2 Demo applications and other examples

The demo applications demonstrate the usage of the peripheral drivers to achieve a system level solution. Each demo application contains a readme file that describes the operation of the demo and required setup steps.

The driver examples demonstrate the capabilities of the peripheral drivers. Each example implements a common use case to help demonstrate the driver functionality.

The RTOS and middleware folders each contain examples demonstrating the use of the included source.

### 6.2 Middleware

#### 6.2.1 USB stack

See the MCUXpresso SDK USB Stack User's Guide (document USBSUG) for more information.

### 6.2.1.1 Peripheral devices tested with the USB Host stack

This table provides a list of USB devices tested with the USB Host stack.

Table 3. Peripheral devices

Device type	Device
USB HUB	BELKIN F5U233
	BELKIN F5U304
	BELKIN F5U307
	BELKIN F4U040
	UNITEK Y-2151
	Z-TEK ZK032A
	HYUNDAI HY-HB608
USB flash drive	ADATA C008 32 GB
	ADATA S102 8 G
	ADATA S102 16 G
	Verbatim STORE N GO USB Device 8 G
	Kingston DataTraveler DT101 G2
	SanDisk Cruzer Blade 8 GB
	Unisplendour 1 G
	Imation 2 GB
	V-mux 2 GB
	Sanmina-SCI 128 M
	Corporate Express 1 G
	TOSHIBA THUHYBS-008G 8 G

Table continues on the next page...

Table 3. Peripheral devices (continued)

	Transcend JF700 8 G
	Netac U903 16 G
	SSK SFD205 8 GB
	Rex 4 GB
	SAMSUNG USB3.0 16GB
USB card reader/adapter	SSK TF adapter
	Kawau Multi Card Reader
	Kawau TF adapter
	Kawau SDHC card
USB Mouse	DELL MS111-P
	DELL M066U0A
	DELL MUAVDEL8
	TARGUS AMU76AP
	DELL MD56U0
	DELL MS111-T
	RAPOO M110
USB Keyboard	DELL SK8135
	DELL SK8115

### 6.2.2 File system

The FatFs file system is integrated with MCUXpresso SDK and can be used to access either the SD card or the USB memory stick when the SD card driver or the USB Mass Storage Device class implementation is used.

### 6.2.3 RTOS

The MCUXpresso SDK is integrated with FreeRTOS OS.

### 6.2.4 CMSIS

The MCUXpresso SDK is shipped with the standard CMSIS development pack, including the prebuilt libraries.

# 7 MISRA compliance

All MCUXpresso SDK drivers and USB stack comply to MISRA 2004 rules with the following exceptions.

MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 03/2018

#### **Known issues**

Exception Rules	Description
1.1	All code shall conform to ISO 9899:1990 Programming languages - C, amended and corrected by ISO/IEC 9899/COR1:1995, ISO/IEC 9899/AMD1:1995, and ISO/IEC
2.4	Sections of code should not be commented out.
5.1	Identifiers (internal and external) shall not rely on the significance of more than 31 characters.
6.3	typedefs that indicate size and signedness should be used in place of the basic types.
6.4	Bitfields shall only be defined to be of type unsigned int or signed int.
8.1	Functions shall have prototype declarations and the prototype shall be visible at both the function definition and call.
8.5	There shall be no definitions of objects or functions in a header file.
8.1	All declarations and definitions of objects or functions at file scope shall have internal linkage unless external linkage is required.
8.12	When an array is declared with external linkage, its size shall be stated explicitly or defined implicitly by initialization.
9	The value of an expression of integer type shall not be implicitly converted to a different underlying type if:
	a. it is not a conversion to a wider integer type of the same signedness, or
	b. the expression is complex, or
	c. the expression is not constant and is a function argument, or
10.1	d. the expression is not constant and is a return expression.
10.3	The value of a complex expression of integer type shall only be cast to a type that is not wider and of the same signedness as the underlying type of the expression.
11.3	A cast should not be performed between a pointer type and an integral type.
11.4	A cast should not be performed between a pointer to object type and a different pointer to object type.
11.5	A cast shall not be performed that removes any const or volatile qualification from the type addressed by a pointer.
12.2	The value of an expression shall be the same under any order of evaluation that the standard permits.
12.4	The right-hand operand of a logical && or     operator shall not contain side effects.
12.6	The operands of logical operators (&&,    , and !) should be effectively boolean. Expressions that are effectively boolean should not be used as operands to operators other than (&&,    , !, =, ==, !=, and ?:).
12.13	The increment (++) and decrement () operators should not be mixed with other operators in an expression.
14.3	Before preprocessing, a null statement shall only occur on a line by itself; it may be followed by a comment, provided that the first character following the null statement is a whitespace character.
14.5	The continue statement shall not be used.
14.7	A function shall have a single point of exit at the end of the function.
16.1	Functions shall not be defined with a variable number of arguments.
17.4	Array indexing shall be the only allowed form of pointer arithmetic.
18.4	Unions shall not be used.
19.1	#include statements in a file should only be preceded by other preprocessor directives or comments.
19.1	In the definition of a function-like macro, each instance of a parameter shall be enclosed in parentheses unless it is used as the operand of # or ##.
20.4	Dynamic heap memory allocation shall not be used.
20.9	The input/output library <stdio.h> shall not be used in production code.</stdio.h>

Figure 1. MISRA exceptions

### 8 Known issues

# 8.1 Maximum file path length in Windows® 7 Operating System

Windows 7 operating system imposes a 260 character maximum length for file paths. When installing the MCUXpresso SDK, place it in a directory close to the root to prevent file paths from exceeding the maximum character length specified by the Windows operating system. The recommended location is the C:\nxp folder.

# 8.2 USB HUB Power supply

The external power supply of the USB HUB must be provided before it can be used. The development board power is not enough to supply multi-level USB HUBs and connected devices. Therefore, the external USB HUB that is connected to the development board should have its own power supply.

### 8.3 USBFS controller issue

Because of the USBFS controller design issues, the USB host suspend/resume demos (usb\_suspend\_resume\_host\_hid\_mouse) of the full speed controller do not support the low-speed device directly.

#### 8.4 USB PID issue

Because the PID of all USB device examples is updated, uninstall the device drivers and then reinstall when the device (with new PID) is plugged in the first time.

# 8.5 New project in MCUXpresso sometimes cannot be built

In KDS 3.2, a new project is created by selecting 'File' -> 'New' -> 'Kinetis SDK 2.x Project'. If you select `All drivers` but do not select RTOS, the project will contain the freertos/portable/heap\_4.c file, which cannot be built. As a workaround, remove the FreeRTOS folder with all content from your project, because these files are only needed for FreeRTOS.

### 8.6 IAR build warning for 8.22.1

The IAR 8.22.1 has an integrated CMSIS 5.3.0 core inside while the current SDK package is using CMSIS 5.1.0, so the following build warning pops ups while compiling IAR projects in the package.

Warning: The header file 'cmsis\_iar.h' is obsolete and should not be used.

A suitable version is automatically included from the CMSIS-core package. This file will be removed in a future release.

# MCUXpresso SDK Release Notes Supporting TWR-K24F120M

**Change Logs** 

# **Contents**

<b>Driver C</b>	hange Log 1
	ADC16
	CMP
	CMT
	CRC
	DAC
	DMAMUX
	DSPI
	EDMA 3
	EWM
	FLASH
	FTM
	GPIO
	12C
	LLWU 7
	LPTMR
	PDB
	PIT 7
	PMC 7
	PORT
	RCM

	Contents	Page
	Title	Number
	RTC	8
	SAI	8
	SIM	9
	SMC	9
	<b>UART</b>	10
	<b>VREF</b>	10
	<b>WDOG</b>	11
	CLOCK	11
Middlev	ware Change Log	12
	DMA_MANAGER	12
	EMVL1 for KSDK	12
	FatFs for KSDK	12
	SDMMC	13
	USB stack for KSDK	15
RTOS (	Change Log	19
	FreeRTOS for KSDK	19

# 1 Driver Change Log

#### ADC<sub>16</sub>

The current ADC16 driver version is 2.0.0.

- 2.0.0
  - Initial version

#### **CMP**

The current CMP driver version is 2.0.0.

- 2.0.0
  - Initial version

#### **CMT**

The current CMT driver version is 2.0.1.

- 2.0.1
  - Miscellaneous changes:
    - \* Added static to global CMT variables
- 2.0.0
  - Initial version

#### **CRC**

The current CRC driver version is 2.0.1.

- 2.0.1
  - Bug fix:
    - \* DATA and DATALL macro definition moved from header file to source file
- 2.0.0
  - Initial version

#### DAC

The current DAC driver version is 2.0.1.

- 2.0.1
  - Bug fix:
    - \* Move the default DAC\_Enable(..., true) from DAC\_Init() to the application code so users

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

#### can enable the DAC's output

2.0.0

Initial version

#### **DMAMUX**

The current DMAMUX driver version is 2.0.2.

- 2.0.2
  - New feature:
    - \* Added an always-on enable feature to a DMA channel for ULP1 DMAMUX support
- 2.0.1
  - Bug fix:
    - \* Fixed build warning while setting the DMA request source in DMAMUX\_SetSource-Change issue by changing the type of the parameter source from uint8\_t to uint32\_t
- 2.0.0
  - Initial version

#### **DSPI**

The current dspi driver version is 2.2.0.

- 2.2.0
  - New feature:
    - \* Added gasket feature for SPI EDMA driver, which reduces one channel used in the EDMA master transfer. With this feature support, only two channels are needed. For example, if the gasket feature is supported, we could use the DSPI\_MasterTransfer-CreateHandleEDMA function like below: DSPI\_MasterTransferCreateHandleEDMA(E-XAMPLE\_DSPI\_MASTER\_BASEADDR, &g\_dspi\_edma\_m\_handle, DSPI\_Master-UserCallback, &userData, &dspiEdmaMasterRxRegToRxDataHandle, NULL, &dspi-EdmaMasterIntermediaryToTxRegHandle);
    - \* Added dummy data setup API to allow users to configure the dummy data to be transferred.
    - \* Added new APIs for half-duplex transfer function. Users can send and receive data by one API in the polling/interrupt/EDMA way, and users can choose to either transmit first or receive first. Additionally, the PCS pin can be configured as assert status in transimission (between transmit and receive) by setting the isPcsAssertInTransfer to true.
- 2.1.4
  - Bug Fix:
    - \* DSPI EDMA driver: The DSPI instance that has separated so the DMA request source can now transfer up to 32767 Bytes data in one DSPI\_MasterTransferEDMA() transfer.
- 2.1.3
  - Bug Fix:

MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- \* DSPI EDMA driver can no longer support the case that the transfer data size is odd, but the bitsPerFrame is greater than 8.
- Optimization:
  - \* Added #ifndef/#endif to allow users to change the default TX value at compile time.
- 2.1.2
  - Bug Fix:
    - \* DSPI\_MasterTransferBlocking function would hang in some corner cases (for example, some cases with bitsPerFrame is 4,6 and kDSPI\_MasterPcsContinuous transfer mode).
- 2.1.1
  - Bug Fix:
    - \* Set the EOQ (End Of Queue) bit to TRUE for the last transfer in transactional APIs.
- 2.1.0
  - New Features:
    - \* Added Transfer prefix in transactional APIs.

#### **EDMA**

The current EDMA driver version is 2.1.2.

- 2.1.2
  - Improvement:
    - \* Added interface to get next TCD address
    - \* Added interface to get the unused TCD number
- 2.1.1
  - Improvement:
    - \* Added documentation for eDMA data flow when scatter/gather is implemented for the EDMA\_HandleIRQ API
    - \* Updated and corrected some related comments in the EDMA\_HandleIRQ API and edmahandle t struct
- 2.1.0
  - Improvement:
    - \* Changed the EDMA\_GetRemainingBytes API into EDMA\_GetRemainingMajorLoop-Count due to eDMA IP limitation (see API comments/note for further details)
- 2.0.5
  - Improvement:
    - \* Added pubweak DriverIRQHandler for K32H844P (16 channels shared)
- 2.0.4
  - Improvement:
    - \* Added support for SoCs with multiple eDMA instances
    - \* Added pubweak DriverIRQHandler for KL28T DMA1 and MCIMX7U5 M4
- 2.0.3
  - Bug fix:
    - \* Fixed the wrong pubweak IRQHandler name issue, which causes re-definition build errors when client sets his/her own IRQHandler, by changing the 32-channel IRQHandler name

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

#### to DriverIRQHandler

- 2.0.2
  - Bug fix:
    - \* Fixed incorrect minorLoopBytes type definition in \_edma\_transfer\_config struct, and defined minorLoopBytes as uint32\_t instead of uint16\_t
- 2.0.1
  - Bug fix:
    - \* Fixed the eDMA callback issue (which did not check valid status) in EDMA\_HandleIRQ API
- 2.0.0
  - Initial version

#### **EWM**

The current EWM driver version is 2.0.1.

- 2.0.1
  - Fixed EWM\_Deinit hardfault issue
- 2.0.0
  - Initial version

#### **FLASH**

The current FLASH driver version is 2.3.1.

- 2.3.1
  - Bug fixes:
    - \* Unified Flash IFR design from K3.
    - \* New encoding rule for K3 flash size.
- 2.3.0
  - New features:
    - \* Added support for device with LP flash (K3S/G).
    - \* Added flash prefetch speculation APIs.
  - Improvements:
    - \* Refined flash cache clear function.
    - \* Reorganized the member of flash\_config\_t struct.
- 2.2.0
  - New features:
    - \* Supports FTFL device in FLASH\_Swap API.
    - \* Supports various pflash start addresses.
    - \* Added support for KV58 in cache clear function.
    - \* Added support for device with secondary flash (KW40).
  - Bug fixes:
    - \* Compiled execute-in-ram functions as PIC binary code for driver use.

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- \* Added missed flexram properties.
- \* Fixed unaligned variable issue for execute-in-ram function code array.
- 2.1.0
  - Improvements:
    - \* Updated coding style to align with KSDK 2.0.
    - \* Different alignment size support for pflash and flexnvm.
    - \* Improved the implementation of execute-in-ram functions.
- 2.0.0
  - Initial version.

#### **FTM**

The current FTM driver version is 2.0.3.

- 2.0.3
  - Bug fixes:
    - \* Updated the FTM driver to enable fault input after configuring polarity.
- 2.0.2
  - Features:
    - \* Added support to Quad Decoder feature with new APIs:
      - FTM\_GetQuadDecoderFlags()
      - · FTM\_SetQuadDecoderModuloValue()
      - FTM\_GetQuadDecoderCounterValue()
      - · FTM ClearQuadDecoderCounterValue()
- 2.0.1
  - Bug fixes:
    - \* Updated the FTM driver to fix write to ELSA and ELSB bits.
    - \* FTM combine mode: set the COMBINE bit before writing to CnV register.
- 2.0.0
  - Initial version.

#### **GPIO**

The current driver version is 2.2.1.

- 2.2.1:
  - API interface changes:
    - \* Refined naming of API while keep all original APIs by marking them as deprecated. Original API will be removed in next release. The mainin change is update API with prefix of \_PinXXX() and \_PorortXXX.
- 2.1.1:
  - API interface changes:
    - \* Added API for the check attribute bytes.
- 2.1.0:

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- API interface changes:
  - \* Added "pins" or "pin" to some APIs' names.
  - \* Renamed "\_PinConfigure" to "GPIO\_PinInit".

#### I2C

The current I2C driver version is 2.0.5.

- 2.0.5
  - Improvements:
    - \* Added I2C\_WATI\_TIMEOUT macro to allow the user to specify the timeout times for waiting flags in functional API and blocking transfer API.
- 2.0.4
  - Bug fixes:
    - \* Added proper handle for transfer config flag kI2C\_TransferNoStartFlag to support transmit with kI2C\_TransferNoStartFlag flag. Only supports write only or write+read with no start flag, does not support read only with no start flag.
- 2.0.3
  - Bug fixes:
    - \* Removed enableHighDrive member in the master/slave configuration structure because the operation to HDRS bit is useless, user needs to use DSE bit in port register to configure the high drive capability.
    - \* Added reset registers operation in I2C\_MasterInit and I2C\_SlaveInit APIs. Fixed issue where I2C could not switch between master and slave mode.
    - \* Improved slave IRQ handler to handle the corner case that stop flag and address match flag come synchronously.
- 2.0.2
  - Bug fixes:
    - \* Fixed issue in master receive and slave transmit mode with no stop flag. The master could not succeed to start next transfer because the master could not send out re-start signal.
    - \* Fixed data transfer out of order issue due to memory barrier
    - \* Added hold time configuration for slave. By leaving the SCL divider and MULT reset values when configure to slave mode, the setup and hold time of the slave is then reduced outside of spec for lower baudrates. This can cause intermittent arbitration loss on the master side.
  - New features:
    - \* Added address nak event for master.
    - \* Added general call event for slave.
- 2.0.1
  - New features:
    - \* Added double buffer enable configuration for Socs which have the DFEN bit in S2 register.
    - \* Added flexible transmit/receive buffer size support in I2C\_SlaveHandleIRQ.
    - \* Added start flag clear, address match, and release bus operation in I2C\_SlaveWrite/Read-Blocking API.

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- Bug fix:
  - \* Changed the kI2C\_SlaveRepeatedStartEvent to kI2C\_SlaveStartEvent.

#### **LLWU**

The current LLWU driver version is 2.0.1.

- 2.0.1
  - Miscellaneous changes:
    - \* Updates for KL8x.
- 2.0.0
  - Initial version.

#### **LPTMR**

The current LPTMR driver version is 2.0.1.

- 2.0.1
  - Driver updates:
    - \* Updated LPTMR driver due to the register LPTMRx\_CMR/CNR in some devices becomes 32 bit, so updated LPTMR driver to support the 32 bit CNR and CMR register.
- 2.0.0
  - Initial version.

#### **PDB**

The current PDB driver version is 2.0.1.

- 2.0.1
  - Changed PDB register base array to const.
- 2.0.0
  - Initial version.

#### **PIT**

The current PIT driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### **PMC**

THe current PMC driver version is 2.0.0.

MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- 2.0.0
  - Initial version.

#### **PORT**

The current PORT driver version is 2.0.2.

- 2.0.2:
  - Miscellaneous changes:
    - \* Added feature guard macros in the driver.
- 2.0.1:
  - Miscellaneous changes:
    - \* Added "const" in function parameter.
    - \* Updated some enumeration variables' names.

#### **RCM**

The current RCM driver version is 2.0.1.

- 2.0.1
  - [KPSDK-10249] Fixed kRCM\_SourceSw bit shift issue.
- 2.0.0
  - Initial version.

#### **RTC**

The current RTC driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### SAI

The current SAI driver version is 2.1.3.

- 2.1.3
  - New features:
    - \* Added feature to make I2S frame sync length configurable according to bitWidth.
- 2.1.2
  - Bug fixes:
    - \* Added 24-bit support for SAI EDMA transfer. All data shall be 32 bits for send/receive, as EDMA cannot directly handle 3 byte transfer.
- 2.1.1

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- Optimization:
  - \* Reduce code size while not using transactional API.
- 2.1.0
  - API name change:
    - \* SAI\_GetSendRemainingBytes -> SAI\_GetSentCount.
    - \* SAI\_GetReceiveRemainingBytes -> SAI\_GetReceivedCount.
    - \* All transcational API name add "Transfer" prefix.
    - \* All transactional API use base and handle as input parameter.
    - \* Unify the parameter names.
  - Bug fixes:
    - \* Fixed w1c bug while reading TCSR/RCSR registers.
    - \* Fixed MOE enable flow issue, move MOE enable after MICS settings in SAI\_TxInit/SA-I RxInit.
- 2.0.0
  - Initial version.

#### SIM

The current SIM driver version is 2.1.0.

- 2.1.0
  - Add new APIs of SIM\_GetRfAddr() and SIM\_EnableSystickClock().
- 2.0.0
  - Initial version.

#### **SMC**

The current SMC driver version is 2.0.3.

- 2.0.3
  - Added APIs SMC\_PreEnterStopModes, SMC\_PreEnterWaitModes, SMC\_PostExitWait-Modes, and SMC\_PostExitStopModes.
- 2.0.2
  - Bug fixes:
    - \* Added DSB before WFI, add ISB after WFI.
  - Miscellaneous changes:
    - \* Updated SMC\_SetPowerModeVlpw implementation.
- 2.0.1
  - Misc Changes:
    - \* Update for KL8x.
- 2.0.0
  - Initial version.

MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

10

#### **UART**

The current UART driver version is 2.1.5.

- 2.1.5
  - Added hardware flow control function support.
  - Added idle line detected feature in UART\_TransferNonBlocking function. If an idle line is detected, a callback is triggered with status kStatus\_UART\_IdleLineDetected returned. This feature may be useful when the received bytes is less than the expected receive data size. Before triggering the callback, data in the FIFO is read out (if it has FIFO), and all interrupts are not be disabled except if the receive data size reaches 0.
  - Enabled the RX FIFO watermark function. With the idle line detected feature enabled, you can
    set the watermark value to whatever you want (should not be bigger than the RX FIFO size).
    Data is then received and a callback is triggered when data receive ends.
- 2.1.4
  - Changed parameter type in UART\_RTOS\_Init() struct rtos\_uart\_config -> uart\_rtos\_configt.
  - Bug fixed:
    - \* Disabled UART receive interrupt instead of disable all NVIC when read data from ring buffer. Because with ring buffer is used, receive nonblocking disables all NVIC interrupts to protect the ring buffer. This has a negative effect to other IPS which are using interrupt.
- 2.1.3
  - Added RX framing error and parity error status check when use interrupt transfer.
- 2.1.2
  - Fixed baud rate fine adjust bug to make the computed baud rate more accurately.
- 2.1.1
  - Removed needless check of event flags and assert in UART\_RTOS\_Receive.
  - Waited always for RX event flag in UART RTOS Receive.
- 2.1.0
  - Added transactional API.
- 2.0.0
  - Initial version.

#### **VREF**

The current VREF driver version is 2.1.0.

- 2.1.0
  - Added new functions:
    - \* Supported L5K board: add VREF\_SetTrim2V1Val() and VREF\_GetTrim2V1Val() functions to supply 2V1 output mode.
- 2.0.0
  - Initial version.

11

#### **WDOG**

The current WDOG driver version is 2.0.0.

- 2.0.0
  - Initial version.

#### **CLOCK**

Current CLOCK driver version is 2.2.1

- 2.0.0
  - Initial version.
- 2.1.0
  - Other Changes:
    - \* Merge fsl\_mcg and fsl\_osc into fsl\_clock.
- 2.2.0
  - New Features:
    - \* [KPSDK-9157] Update CLOCK\_SetFeiMode/CLOCK\_SetFbiMode/CLOCK\_BootTo-FeiMode() to support set MCG\_C4[DMX32]=1 in FEI/FBI modes.
  - Bug Fix:
    - \* Update IP\_CLOCKS array, remove unused gates and add missing gates.
- 2.2.1
  - Bug Fix:

**NXP Semiconductors** 

\* Fix the issue that MCG could not switch to FEE/FBE/PBE modes when OSCERCLK clock not enabled.

# 2 Middleware Change Log

### **DMA MANAGER**

The current DMA\_MANAGER driver version is 2.1.0.

- 2.1.0
  - Updated DMA manager interface to support dynamic configure the manage area. This is used for a platform with multiple cores.
- 2.0.0
  - Initial version.

#### EMVL1

The current driver version is 2.1.0.

- 2.0.0
  - Initial version.
- 2.0.1
  - Bug fix:
    - \* Fixed low-level driver protocol timers failures during emvl1 pre-certification tests (KPS-DK-9556).
    - \* Fixed improper T0 commands response receiving (commands case2, case3 & case4 affected) what causes long commands responses (KPSDK-8707).
- 2.0.2
  - Re-implemented function for sending commands in T=0.
  - Bug fix:
    - \* Fixed wrong size of response in T=0 (KPSDK-11248).
    - \* Fixed problem with command cases 3 in T=1, expected wrong length of response (KPS-DK-11335).
    - \* Fixed wrong length of response in T=1 (KPSDK-11868).
    - \* Fixed usage application buffer for data payload and overhead associated with T=1 protocol (KPSDK-11336).
- 2.1.0
  - Added abort transfer functionality.

#### **FatFs**

The current version is FatFs R0.12c.

- R0.12c rev0
  - Upgraded to version 0.12c and apply patches ff\_12c\_p1.diff and ff\_12c\_p2.diff.
- R0.12b rev0

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- Upgraded to version 0.12b.
- R0.11a
  - Added glue functions for low level drivers (SDHC, SDSPI, RAM, MMC). Modified diskio.c.
  - Added RTOS wrappers to make FatFs thread safe. Modified syscall.c.
  - Renamed ffconf.h to ffconf template.h. Each application should contain its own ffconf.h.
  - Included ffconf.h into diskio.c to enable selection of physical disk from ffconf.h by macro definition.
  - Conditional compilation of physical disk interfaces in diskio.c.

#### **SDMMC**

The current driver version is 2.2.4.

- 2.2.4
  - Bug fix:
    - \* Fixed DDR mode data sequence mess issue which caused by NIBBLE\_POS.
  - New features:
    - \* Increased g\_sdmmc 512byte to improve the performance when application use a non-word align data buffer address.
    - \* Used OCR access mode bits to determine the mmccard high capacity flag.
    - \* Enabled auto cmd12 for SD read/write.
    - \* Disabled DDR mode frequency multiply by 2.
- 2.2.3
  - Bug fix:
    - \* Added reponse check for send operation condition command. If not checked, the card may occasionally init fail.
- 2.2.2
  - Moved set card detect priority operation before enable IRQ.
- 2.2.1
  - New features:
    - \* Improved MMC Boot feature.
    - \* Keep SD\_Init/SDIO\_Init function for forward compatibility.
- 2.2.0
  - New features:
    - \* Separated the SD/MMC/SDIO init API to xxx\_CardInit/xxx\_HostInit.
    - \* Allowed user register card detect callback, select card detect type, and determine the card detect timeout value.
    - \* Allowed user register the power on/off function, and determine the power on/off delay time.
    - \* SD Init/SDIO Init will be deprecated in the next version.
    - \* Added write complete wait operation for MMC\_Write to fix command timeout issue.
- 2.1.6
  - Enhanced SD IO default driver strength.
- 2.1.5

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- Fixed coverity issue.
- Fixed SD v1.x card write fail issue. It was caused by the block length set error.
- Improved SDIO card init sequence and add retry option for SDIO\_SwitchToHighSpeed function.

#### • 2.1.4

- Miscellaneous:
  - \* Added Host reset function for card re-initialization.
  - \* Added Go\_Idle function for SDIO card.
  - \* Added Host\_ErrorRecovery function for host error recovery procedure.
  - \* Added cache maintain operation
  - \* Added HOST\_CARD\_INSERT\_CD\_LEVEL to improve compatibility.
- Bug fix:
  - \* Fixed card cannot detect dynamically.

#### • 2.1.3

- Bug fix:
  - \* Non high-speed sdcard init fail at switch to high speed.
- Miscellaneous:
  - \* Optimized tuning/mmc switch voltage/mmc select power class/mmc select timing function
  - \* Added strobe dll for mmc HS400 mode.
  - \* Added Delay for SDCard power up.

#### • 2.1.2

- New features:
  - \* Added fsl\_host.h to provide prototype to adapt different controller IPs(SDHC/SDIF).
  - \* Added adaptor code in SDMMC/Port folder to adapt different host controller IPs with different. transfer modes(interrupt/polling/freertos). Application includes a different adaptor code to make application more simple.
  - \* Adaptor code provides HOST\_Init/HOST\_Deinit/CardInsertDetect. APIs to do host controller initialize and transfer function configuration. SDMMC card stack uses adaptor code inside stack to wait card insert and configure host when calling card init APIs (SD\_Init/MMC\_Init/SDIO\_Init).
  - \* This change requires the user to include host adaptor code into the application. If not changed, link errors saying it cannot find the definition of HOST\_Init/HOST\_Deinit/-CardInsertDetect appear.
- New features: Improved SDMMC to support SD v3.0 and emmc v5.0.
- Bug fix:
  - \* Fixed wrong comparison between count and length in MMC\_ReadBlocks/MMC\_Write-Blocks.

### • 2.1.1

- Bug fix:
  - \* Fixed the block range boundary error when transferring data to MMC card.
  - \* Fixed the bit mask error in the SD card switch to high speed function.
- Other changes:
  - \* Added error code to indicate that SDHC ADMA1 transfer type is not supported yet.
  - \* Optimized the SD card initialization function.

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- 2.1.0
  - Bug fix:
    - \* Change the callback mechanism when sending a command.
    - \* Fix the performance low issue when transferring data.
  - Other changes:
    - \* Changed the name of some error codes returned by internal function.
    - \* Merged all host related attributes to one structure.
    - \* Optimize the function of setting maximum data bus width for MMC card.

#### **USB** stack

The current version of USB stack is 1.9.0.

- 2.0.0
  - New features:
    - \* PTN5110N support.
  - Bug fixes:
    - \* Added some comments, fixed some minor USB issues.
- 1.9.0
  - New features:
    - \* Examples
      - · usb\_pd\_alt\_mode\_dp\_host
- 1.8.2
  - Updated licnese.
- 1.8.1
  - Bug fixes:
    - \* Verified some hardware issues, supports aruba\_flashless.
- 1.8.0
  - New features:
    - \* Examples:
      - usb\_device\_composite\_cdc\_vcom\_cdc\_vcom
      - · usb\_device\_composite\_hid\_audio\_unified
      - · usb\_pd\_sink\_battery
      - · Change usb\_pd\_battery to usb\_pd\_charger\_battery
- Bug fixes:
  - Code clean up, removed some irrelevant code.
  - 1.7.0
    - New features:
      - \* USB PD stack support.
    - Examples:
      - \* usb\_pd
      - \* usb\_pd\_battery
      - \* usb\_pd\_source\_charger

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- 1.6.3
  - Bug fixes: -IP3511\_HS driver control transfer sequence issue, enabled 3511 ip cv test.
- 1.6.2
  - New features:
    - \* Multi-instance support
- 1.6.1
  - New features:
  - Changed the struct variable address method for device\_video\_virtual\_camera and host\_phdc-manager.
- 1.6.0
  - New features:
    - \* Supported Device Charger Detect feature on usb device hid mouse.
- 1.5.0
  - New features:
    - \* Supported controllers
      - · OHCI (Full Speed, Host mode)
      - · IP3516 (High Speed, Host mode)
      - · IP3511 (High Speed, Device mode)
    - \* Examples
      - · usb\_lpm\_device\_hid\_mouse
      - · usb\_lpm\_device\_hid\_mouse\_lite
      - · usb\_lpm\_host\_hid\_mouse
- 1.4.0
  - New features:
    - \* Examples
      - · usb\_device\_hid\_mouse/freertos\_static
      - · usb\_suspend\_resume\_device\_hid\_mouse\_lite
- 1.3.0
  - New features:
    - \* Supported roles:
      - · OTG
    - \* Supported classes:
      - · CDC RNDIS
    - \* Examples:
      - · usb\_otg\_hid\_mouse
      - · usb device cdc vnic
      - · usb\_suspend\_resume\_device\_hid\_mouse
      - · usb\_suspend\_resume\_host\_hid\_mouse
- 1.2.0
  - New features:
    - \* Supported controllers
      - · LPC IP3511 (Full Speed, Device mode)
- 1.1.0
  - Bug fixes:
    - \* Fixed some issues in USB certification.

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- \* Changed VID and Manufacturer string to NXP.
- New features:
  - \* Supported classes
    - · Pinter
  - \* Examples:
    - · usb\_device\_composite\_cdc\_msc\_sdcard
    - · usb\_device\_printer\_virtual\_plain\_text
    - · usb\_host\_printer\_plain\_text
- 1.0.1
  - Bug fixes:
    - \* Improved the efficiency of device audio speaker by changing the transfer mode from interrupt to DMA, thus eliminating the periodic noise.
- 1.0.0
  - New features:
    - \* Supported roles
      - · Device
      - · Host
    - \* Supported controllers:
      - · KHCI (Full Speed)
      - · EHCI (High Speed)
    - \* Supported classes:
      - · AUDIO
      - · CCID
      - · CDC
      - · HID
      - · MSC
      - · PHDC
      - · VIDEO
    - \* Examples:
      - · usb\_device\_audio\_generator
      - · usb\_device\_audio\_speaker
      - · usb\_device\_ccid\_smart\_card
      - · usb\_device\_cdc\_vcom
      - · usb\_device\_cdc\_vnic
      - usb\_device\_composite\_cdc\_msc
      - · usb device composite hid audio
      - · usb\_device\_composite\_hid\_mouse\_hid\_keyboard
      - · usb\_device\_hid\_generic
      - · usb\_device\_hid\_mouse
      - · usb\_device\_msc\_ramdisk
      - · usb device msc sdcard
      - · usb\_device\_phdc\_weighscale
      - · usb device video flexio ov7670
      - · usb\_device\_video\_virtual\_camera
      - · usb\_host\_audio\_speaker

#### MCUXpresso SDK Release Notes Supporting TWR-K24F120M, Rev. 0, 3/2018

- · usb\_host\_cdc
- · usb\_host\_hid\_generic
- · usb\_host\_hid\_mouse
- · usb\_host\_hid\_mouse\_keyboard
- $\cdot \ usb\_host\_msd\_command$
- · usb\_host\_msd\_fatfs
- · usb\_host\_phdc\_manager
- · usb\_keyboard2mouse
- · usb\_pin\_detect\_hid\_mouse

# 3 RTOS Change Log

#### **FreeRTOS**

The current version is FreeRTOS 9.0.0. Original package is available at freertos.org.

- 9.0.0 rev3
  - New features:
    - \* Tickless idle mode support for Cortex-A7. Add fsl\_tickless\_epit.c and fsl\_tickless\_generic.h in portable/IAR/ARM\_CA9 folder.
    - \* Enabled float context saving in IAR for Cortex-A7. Added configUSE\_TASK\_FPU\_SU-PPORT macros. Modified port.c and portmacro.h in portable/IAR/ARM\_CA9 folder.
  - Other changes:
    - \* Transformed ARM\_CM core specific tickless low power support into generic form under freertos.
- 9.0.0 rev2
  - New features:
    - \* Enabled MCUXpresso thread aware debugging. Add freertos\_tasks\_c\_additions.h and configINCLUDE\_FREERTOS\_TASK\_C\_ADDITIONS\_H and configFRTOS\_MEMORY SCHEME macros.
- 9.0.0 rev1
  - New features:
    - \* Enabled -flto optimization in GCC by adding attribute((used)) for vTaskSwitchContext.
    - \* Enabled KDS Task Aware Debugger. Apply FreeRTOS patch to enable configRECORD\_STACK\_HIGH\_ADDRESS macro. Modified files are task.c and FreeRTOS.h.
- 9.0.0 rev0
  - New features:
    - \* Example freertos\_sem\_static.
    - \* Static allocation support RTOS driver wrappers.
  - Other changes:
    - \* Tickless idle rework. Support for different timers is in separated files (fsl\_tickless\_systick.c, fsl\_tickless\_lptmr.c).
    - \* Removed configuration option configSYSTICK\_USE\_LOW\_POWER\_TIMER. Low power timer is now selected by linking of apropriate file fsl\_tickless\_lptmr.c.
    - \* Removed configOVERRIDE\_DEFAULT\_TICK\_CONFIGURATION in RVDS port. Use of **attribute**((weak)) is preffered solution. Not same as week!
- 8.2.3
  - New features:
    - \* Tickles idle mode support.
    - \* Added template application for Kinetis Expert (KEx) tool (template\_application).
  - Other changes:
    - \* Folder structure reduction. Keep only Kinetis related parts.

#### How to Reach Us:

Home Page:

nxp.com

Web Support:

nxp.com/support

Information in this document is provided solely to enable system and software implementers to use NXP products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits based on the information in this document. NXP reserves the right to make changes without further notice to any products herein.

NXP makes no warranty, representation, or guarantee regarding the suitability of its products for any particular purpose, nor does NXP assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters that may be provided in NXP data sheets and/or specifications can and do vary in different applications, and actual performance may vary over time. All operating parameters, including "typicals," must be validated for each customer application by customer's technical experts. NXP does not convey any license under its patent rights nor the rights of others. NXP sells products pursuant to standard terms and conditions of sale, which can be found at the following address: nxp.com/SalesTermsandConditions.

NXP, the NXP logo, NXP SECURE CONNECTIONS FOR A SMARTER WORLD, Freescale, the Freescale logo, Kinetis, and Tower are trademarks of NXP B.V. All other product or service names are the property of their respective owners. Arm, Arm Powered, Cortex, Keil, and µVision are registered trademarks of Arm Limited (or its subsidiaries) in the EU and/or elsewhere. All rights reserved.

© 2018 NXP B.V.

Document Number MCUXSDKK24FRN Revision 0, 03/2018



