Charge R= 252 L- 25mH C= 15 uF batterie No Voul cupacte = 40 Ah Vacaning = 12.8V = 148 13,00 Je 385 for it fat provinte to cut-off vallage de 1800 △V= 10% Mawmerm 0 40% 0 D.75V V marc 10% = (13 V) culabour à 10% Ns = 11,47 % 12 cellules en sièrie Vbatt = LL 330LL over transfo a=2 <= R + C + L 13 = VW Z = 2 + 1/3 (15.10-4) + 1207.25.16-3.3 Vbatt: 148 V OC = LN Z= 2 + 176,83 + 9,4247 J ≥= 9 - 176,8 J + 9,4347 J Z= 2-167,40J S= 2542 5 - 385,37 VA Vnoy = 5.12.875 = 64, 375 V Int. P = S VA = A Ibut = 385.37 = 5,98 A Ibutt / 4019 duc c'est ox Np = 1 cellule en puralèle



