

LEVEL 1	LEVEL 2	LEVEL 3	LEVEL 4	N°
Scara_Assembly				
	Base			
		Frame base		1
		Servomotor_hg-mr13		1
		Hex nut M4 (ISO 4032)		2
		Hex head screw M4×25 (ISO 4017)		14
		Flat washer M4 (ISO 7089)		14
		Slewing ring Ø100 mm		1
		Flexible shaft coupling 8–8 mm		1
	Arm_00_Assembly			
		Hex head screw M4×45 (ISO 4017)		12
		Flat washer M4 (ISO 7089)		16
		Hex nut M4 (ISO 4032)		12
		Waist		1
		Deep groove ball bearing 618-8		1
		Flexible shaft coupling 8–8 mm		1
		Servomotor_hg-mr13		1
		Frame motor		1
		Hex socket head cap screw M4×20 (ISO 4762)		6
	Arm_01_Assembly			
		Frame Arm_01		1
		Deep groove ball bearing 618-8		2
		Joint_12		2
		Flat washer M5 (ISO 7089)		4
		Hex head screw M5×12 (ISO 4017)		4
	Arm_02_Assembly			
		Main frame		1
		Nylon insert lock nut M5 (ISO 10511)		1
		Hex head screw M5×20 (ISO 4017)		1
		Hex nut M4 (ISO 4032)		2

		Plate_motor		1
		Deep groove ball bearing 618-8		1
		Flexible shaft coupling 8-8 mm		1
		Hex head screw M4×20 (ISO 4017)		4
		Motor frame		1
		Flat washer M5 (ISO 7089)		2
		Hex head screw M5×8 (ISO 4017)		2
		Upper frame		1
		Flat washer M4 (ISO 7089)		6
		Hex head screw M4×8 (ISO 4017)		4
		Set screw M4×10 (ISO 4027)		2
		Pulley transmission		1
			GT2 timing pulley - 20 T - 8 mm bore - 10mm belt	1
			GT2 timing pulley 80 T - 8 mm bore - 10 mm belt	1
			GT2 timing belt - 10 mm width	1
			Driven shaft	1
			Deep groove ball bearing 618-8	2
			External retaining ring 8 mm (UNI 7435)	2