

Reports

Generate filtered reports — use Print / Save as PDF to export



Generated: 5 October 2026
Investment Party: **Anuva**
Period: **Sep-26**

Site Performance Report

18 Records		242,954.58 Measured (kWh)		286,858.731 Expected (kWh)		-15.3% Δ vs Expected		7 Expected Band		9 / 2 Moderate / Poor		
Site Name	Period	Measured kWh	Expected kWh	Δ %	Perf %	PF Band	Availability	Downtime	Cause of Downtime	Technical Events	Energy Impact	Other Comments
21 Melrose	Sep-26	1,161.6	2,218.893	-47.6%	52.4%	Poor	30	0	None	None	Energy production was limited by load demand	N/A
Bendstore Plaza Shops	Sep-26	8,314.17	15,033.929	-44.7%	55.3%	Poor	30	0	None	None	Energy production was limited by load demand	N/A
Bendstore Spar	Sep-26	36,563.6	47,682.577	-23.3%	76.7%	Moderate	30	0	None	None	The system performed poorly due to rainy and cloudy weather	N/A
Club Houghton	Sep-26	3,663	4,881.069	-25.0%	75.0%	Moderate	30	0	None	None	Energy production was limited by load demand	N/A
Coldstar International	Sep-26	3,940.14	3,688.748	+6.8%	107.1%	Expected	30	0	None	None	The system performed as expected	N/A
Hilston Rotoflo	Sep-26	22,877.77	24,094.518	-5.0%	95.1%	Expected	30	0	None	None	The system performed as expected	N/A
Kool Village	Sep-26	7,912.61	10,701.9	-26.1%	73.9%	Moderate	30	0	None	None	Energy production was limited by load demand	N/A
Total	18 rows	242,954.58	286,858.731	-15.3%								

Site Name	Period	Measured kWh	Expected kWh	Δ %	Perf %	PF Band	Availability	Downtime	Cause of Downtime	Technical Events	Energy Impact	Other Comments
Mambha Cash & Carry	Sep-26	14,407.68	16,146.881	-10.8%	89.2%	Moderate	30	0	None	None	The system performed poorly due to the load demand reduction, rainy and cloudy weather	N/A
Mathe Group Company	Sep-26	43,037.19	48,830.273	-11.9%	88.1%	Moderate	30	0	None	None	The system performed poorly due to rainy and cloudy weather	N/A
Meredale Heights	Sep-26	5,211.5	5,478.728	-4.9%	95.2%	Expected	30	0	None	None	The system performed as expected	N/A
Monument Park Checkers	Sep-26	33,460.18	35,884.038	-6.8%	93.2%	Expected	30	0	None	None	The system performed as expected	N/A
Opal Students	Sep-26	4,904	5,189.949	-5.5%	94.5%	Expected	30	0	None	None	The system performed as expected	kWh based on inverter readings (per Sep kWh registration)
Plastiplate	Sep-26	6,037.27	8,097.534	-25.4%	74.8%	Moderate	30	0	None	None	Energy production was limited by load demand	N/A
Riverside Lodge	Sep-26	16,094	16,546.481	-2.7%	97.3%	Expected	30	0	None	None	The system performed as expected	N/A
Saverite Durban	Sep-26	7,731.86	8,993.978	-14.0%	86.0%	Moderate	30	0	None	None	The system performed poorly due to the load demand reduction, rainy and cloudy weather	N/A
The Alec	Sep-26	4,853.26	6,201.36	-21.7%	78.3%	Moderate	30	0	None	None	The system performed poorly due to the load demand reduction, rainy and cloudy weather	N/A
Three Peaks	Sep-26	3,170.27	3,223.869	-1.7%	98.3%	Expected	30	0	None	None	The system performed as expected	N/A
Watt Place Rotoflo	Sep-26	19,614.48	23,964.006	-18.2%	81.8%	Moderate	30	0	None	None	The system performed poorly due to the load	N/A
Total	18 rows	242,954.58	286,858.731	-15.3%								

Site Name	Period	Measured	Expected kWh	Δ %	Perf %	PF Band	Availability	Downtime	Cause of Downtime	Technical Events	Energy Impact	Other Comments
		kWh										
demand reduction, rainy and cloudy weather												
Total	18 rows	242,954.58	286,858.731	-15.3%								

One row per site per reporting period, showing measured vs expected generation, performance band, and the technical comments logged for the month. Rows are ordered most-recent period first.
© 2026 Sosimple Energy — Cheap energy. Clean business.