

CSFM2200-010-0008DY

A


B

C

D

E

F



A

B

C

D

E

F

Note 1: VVVF and HB are installed in M3 car;  
Note 2: Only M3 interseccion

|             |                   |                        |  |           |      |                 |         |                                |             |
|-------------|-------------------|------------------------|--|-----------|------|-----------------|---------|--------------------------------|-------------|
|             |                   |                        |  |           |      |                 |         | CSR Qingdao Sifang Co., Ltd.   |             |
|             |                   |                        |  |           |      |                 |         | Traction and Braking Control 2 |             |
| Version     | Number of changes | Corrected document No. |  | Signature | Date |                 |         | Code                           | 34130100009 |
| Designed by |                   |                        |  |           |      | Phase mark      | Quality | Scale                          |             |
| Checked by  |                   |                        |  |           |      | S               | 0       | 1:1                            |             |
| Reviewed by |                   |                        |  |           |      | 1 page in total |         | Page 1                         |             |
| Directed by |                   |                        |  |           |      |                 |         |                                |             |
| General     |                   |                        |  |           |      |                 |         |                                |             |