MATRIX Gesture Sensor MS-017

1.Feature

- · Faster, more accurate...
- · Low Power Consumption.
- · Work in low-light.





2. Application


- · Robot interaction.
- · Gesture light control

3. Introduction

Gesture Sensor (PAJ7620U2) is touchless 3D gesture recognition function with general I2C interface into a single chip.

It can recognize 9 gestures including move up, move down, move left, move right, etc. with a simple swipe of your hand from 5-15cm.

4. Block Diagram



MATRIX Gesture Sensor MS-017

4.Example Code of Block and C++


```
#include "MatrixMiniR4.h"
                                                                               float gestCode;
         18650x2 ▼ UART: On ▼ Baud:
Mini Begin
                                        9600 -
                                                                               void setup()
           Gesture Sensor | I2C1 ▼ | Initialize
                                                                                MiniR4.begin();
                                                                          8
                                                                                MiniR4.PWR.setBattCell(2);
                                                                                Serial.begin(9600);
                                                                          9
Loop
                                                                         10
                                                                                MiniR4.I2C1.MXGesture.begin();
                                                                         11
                                                                         12
                                                                         13
                                                                              void loop()
                                                                         15
                                                                                 gestCode = MiniR4.I2C1.MXGesture.getGesture();
                                                                                if(!(gestCode == 0))
                                                                         16
                                                                         17
                                                                         18
                                                                                   Serial.println(gestCode);
                                                                         19
                                                                         20
```

· After download program into controller, open Serial Monitor to observe.

5. Hardware Spec

· Voltage: 3.3v - 5v

· Current: 4.6mA - 9.2mA



Pinout-I2C			
NO.	Name	I/O	Description
1	SDA	I/O	Serial data line.
2	SCL		Serial clock line.
3	VCC	0	Supply voltage.
4	GND	_	Supply ground.

· For More technical info of Sensor, Please visit <u>manufacturer datasheet</u>.