

MATRIX PIR Motion Sensor MS-012

1.Feature

- · Human Sensing.
- · Low Power Consumption.
- · Sensor Feedback.



- · Home automation.
- · Easy to Use






3. Introduction

The PIR Motion Sensor detects motion by sensing infrared radiation from humans and animals.

It identifies heat signature changes within 7 meters and a 100-degree angle. It is ideal for home automation.

4. Block Diagram



MATRIX PIR Motion Sensor MS-012

4.Example Code of Block and C++

```
#include "MatrixMiniR4.h"
                                                                           2
                                                                               void setup()
Mini Begin 18650x2 ▼ UART: On ▼ Baud: 9600 ▼
                                                                                 MiniR4.begin();
Setup
                                                                                 MiniR4.PWR.setBattCell(2);
                                                                           7
                                                                                 Serial.begin(9600);
Loop
                                                                          10
                                                                               void loop()
             USB Serial Print PIR Detected!
                                                                          11
                                                                                 if(MiniR4.D1.getL())
                                                                          12
                                                                          13
                                                                                    Serial.println("PIR Detected!");
                                                                          15
                                                                          16
                                                                          17
```


· After download program into controller, open Serial Monitor to observe.

5. Hardware Spec

· Voltage: 3.3v - 5v

· Current: 15µA

· Return Value: LOW, HIGH (False, True)



Pinout-Digital Out			
NO.	Name	I/O	Description
1	DOUT	I/O	Digital output
2	NC	-	NC
3	5V	0	Supply voltage
4	GND	-	Supply ground