
Clean commissioning
fit, select, calibrate
Frozen ARX + RBF
reference and threshold
Clean initialization
+ approved commands
Predicted motion
(no measurement update)
Residual score
+ return evidence
Current measurements
Alarm state + counter