
ARX(4)
Rolling mean (45)
CUSUM
Following hysteresis
Fused hysteresis
Mode hysteresis
Fixed return
0
10
20
30
40
Benign alarm points (%)
0
20
40
60
80
Events with premature clearing / 90