
Entry exceedance
Dwell while evidence passes
Clearance evidence fails
Benign alarm points
7500
5000
2500
0
7,156
1,198
7,012
1,195
Base dwell10
Base dwell1
RBF dwell10
RBF dwell1
Benign alarm starts / h
1500
1000
500
0
1208
1537
1192
1501
Base dwell10
Base dwell1
RBF dwell10
RBF dwell1