

Work In and Losses Out (ledger) - full run
W base (in)
W bias (in)
E load
D film
D struct (c1, ce)
D wall
Cumulative energy (pJ)
0
20
40
60
80
100
120
0.0
0.1
0.2
0.3
0.4
0.5
Time (s)