Tabela de tolerâncias	
Dimensão	Tolerância
Até 6	±0,1
6 à 30	±0,2
30 à 120	±0,3
120 à 315	±0,5
315 à1000	±0,8





