



## Certified Status of Local Modification

Aircraft Type : BOEING 747-409F

Registration : B-18707 (MSN 30764)

Total page : / page

Prepared by:

C C L

Reviewed by:

Tan Tao Ying

Date :

OCT. 05 2023

A/C Reg. No.	B-18707	Certified Local Mod Status									
TSN	95023.58										
CSN	17475										
Date	2023/10/5										
ITEM	ATA	MODIFICATION TYPE	DESCRIPTION	LOCAL MOD EO	COMPLETION OF LOCAL MODIFICATION			DE-MOD EO	COMPLETION OF DE-MODIFICATION		
					FH	FC	DATE		FH	FC	DATE
1	25	LOCAL MOD	Cockpit License Holders (3 EA) Installation	744-25-00-0011	19423	3299	2005/3/18				
2	25	LOCAL MOD	Medical Pouch (located at UD RH Closet)	744-25-99-0128	54525.71	9448	2013/5/30				
3	25	LOCAL MOD	A/C IDENTIFICATION PLATE INSTALLATION (located in DR 1L Front Frame by rivets)	744-25-99-0140	59824.31	10430	2014/8/19				
4	25	LOCAL MOD	Additional No Smoking Placards in Crew Bunk (total 4 places)	744-25-99-0164	85171.88	15462	2020/11/3				
5	25	LOCAL MOD	Cosmetic Holder Installed in Lav	744-25-99-0171	94033.95	17304	2023/3/10				
6	25	LOCAL MOD	Security Tamper-Evident Seals (UD total 7 places)	MUL-25-99-0023	47690	8108	2011/7/29				
7	25	Contents by CAA Request	FAK	Installed Since Delivery							
8	22	LOCAL MOD	CAT 2/3 STATUS PLACARD INSTALLATION	744-22-00-0001	19	11	2001/4/12				
9	25	LOCAL MOD	744F Nose Head Ceiling Straps - Pit Seam Tape Installation	744-25-59-0001	63066.63	11046	2015/6/23				
10	25	LOCAL MOD	Main Floor Additional Line Marks for pallet loading	744-25-99-0102	53031.9	9148	2012/11/30				
11	25	LOCAL MOD	Loading Mark Lines on Aft Cargo Floor STA 1847/1850	744-25-99-0129	81740.43	14785	2020/2/20				
12	None	LOCAL MOD	Flight awat kit (red) located in bulk cargo	Installed Since Delivery							
13	None	LOCAL MOD	Gear pin & Tie-down strap Box (yellow) located in DR1L front floor	Installed Since Delivery							

CCL