



RMA FORM

Ref No: 1884-5

MATERIAL + IDENTIFICATION CONTROL

QMR/ RO / SAP No. : QMR 26-14754Dispatch Note No. 4038185975

Verification Results (To be filled by RMA coordinator)

- | | |
|---|------------------------------|
| 1. Parts in original box? (Y/ N) | <u>Yes</u> |
| 2. Original quality seal intact? (Y/ N) | <u>Yes</u> |
| 3. Baunumber on packing label | <u>95195245</u> |
| 4. Physical quantity/ Lot(s) | <u>1,326 pcs. / 1 Lot</u> |
| 5. Type of packing | <u>Reel / Dry pack</u> |
| 6. Package type / Device | <u>PG-VQFN-48-37/ S9263U</u> |
| 7. Packing Condition | <u>Original packing</u> |

8. Lot Details

Original Lot #	<u>6HUGYYFMA21</u>		
Datecode	<u>2543</u>		
Quantity	<u>1 x 1326</u>		
Org Seal (Y/ N)	<u>Y</u>		
Strap Intact (Y/ N)	<u>-</u>		
Dry Bag Cond.	<u>Y</u>		
Original Lot #			
Datecode			
Quantity			
Org Seal (Y/ N)			
Strap Intact (Y/ N)			
Dry Bag Cond.			

For > 6 lots , continue to update on Back Page for lot details.

Material Checked by: Kwee YenDate Checked : 23 Jun 2026

SUPPLEMAENTARY MEASURES (WORK INSTRUCTION + FLOW)

(To be filled by QE)

**M9841A (Arkas_UMC or Arkas_CXPI) of
TLE9844QXC**

Reasons of return: _____

Work Flow: Lot received -> Detape, sorting DC/Lot code -> T8-> T1 -> T2-
> Bake-In-> MSP-> Re-pack & Dry Pack-> FC -> Ship to
DCA. (Loose quantity not allowed).

Requires Future hold (Y/N): No If Y, please specify: _____Scrap (Y/N): NoLoose Quantity allowed (Y/ N): YesProduct Engineer: Koh Min Merissa

Special Instructions: _____

Prepared by QM Engineer: Leow Siok Hua

Work Flow

