

**RMA FORM**Ref No: 1884**MATERIAL + IDENTIFICATION CONTROL**QMR/ RO / SAP No. : QMR 26-14754Dispatch Note No. 4038185975**Verification Results** (To be filled by RMA coordinator)

- | | |
|---|------------------------------|
| 1. Parts in original box? (Y/ N) | <u>Yes</u> |
| 2. Original quality seal intact? (Y/ N) | <u>Yes</u> |
| 3. Baunumber on packing label | <u>95195674</u> |
| 4. Physical quantity/ Lot(s) | <u>12,000 pcs. / 1 Lot</u> |
| 5. Type of packing | <u>Reel / Dry pack</u> |
| 6. Package type / Device | <u>PG-VQFN-24-20/ M6937A</u> |
| 7. Packing Condition | <u>Original packing</u> |

8. Lot Details

Original Lot #	<u>ZA44720686N</u>		
Datecode	<u>2621</u>		
Quantity	<u>2 x 6000</u>		
Org Seal (Y/ N)	<u>Y</u>		
Strap Intact (Y/ N)	<u>-</u>		
Dry Bag Cond.	<u>Y</u>		
Original Lot #			
Datecode			
Quantity			
Org Seal (Y/ N)			
Strap Intact (Y/ N)			
Dry Bag Cond.			

For > 6 lots , continue to update on Back Page for lot details.

Material Checked by: Kwee YenDate Checked : 23 Jun 2026**SUPPLEMENTARY MEASURES (WORK INSTRUCTION + FLOW)**

(To be filled by QE)

**M9841A (Arkas_UMC or Arkas_CXPI) of
TLE9844QXC**

Reasons of return: _____

Work Flow: Lot received -> Detape, sorting DC/Lot code -> T8-> T1 -> T2-> Bake-In-> MSP-> Re-pack & Dry Pack-> FC -> Ship to DCA. (Loose quantity not allowed).

Requires Future hold (Y/N): No If Y, please specify: _____Scrap (Y/N): NoLoose Quantity allowed (Y/ N): NoProduct Engineer: Koh Min Merissa

Special Instructions: _____

Prepared by QM Engineer: Leow Siok Hua**Work Flow**