1. Version number changes									
No.	Details	Subject source code	Line	No.					
	Change file header version number to 1.01.00. Change release date.	All files							
2	Change BOOT_MESSAGE version number to 1.01.00.	kernel/sysmain/src/sysmain.h	30	1					
		config/sysdepend/app_at91/utk_config_depend.h	54 56	1					

2. M	easures for bugs			
No.	Details	Subject source code	Line	No.
- 1	Revise the bug. The bug detail: task starts up while in an interrupt-disabled state when dispatching occurs within tk_ena_dsp.	kernel/sysdepend/cpu/at91/cpu_support.S	101	
2	Revise the bug. The bug detail: RUN state is returned if the task in WAIT state is referenced with tk ref tsk or td ref tsk.	kernel/tkernel/src/task_manage.c kernel/tkernel/src/task_manage.c	471 607	
3	Revise the bug. The bug detail: overflow is not detected when count value exceeds the upper limit of INT type, with the sign sem.  New York the bug. The bug details: the WATT state of the subsequent task in the	kernel/tkernel/src/semaphore.c	166	1
4	send queue is not released when the message exceeding the buffer size is	kernel/tkernel/src/messagebuf.c	429	1
5	Revise the bug. The bug detail: if not the message but the send waiting task exists in a message buffer, the message size to be received next time is 0 when referenced with tk ref mbf or td ref mbf.	kernel/tkernel/src/messagebuf.c kernel/tkernel/src/messagebuf.c	458 562	
6	Revise the bug. The bug detail: queue for task waiting for calling when executing tk_fwd_por is always FIFO, without following rendezvous attribute of forwarding destination.	kernel/tkernel/src/rendezvous.c	424	
/	Revise the bug. The bug detail: the task is put in WAIT state when tk_get_mpl is executed by specifying the size larger than variable-size memory pool.	kernel/tkernel/src/mempool.c	445	
8	Revise the bug. The bug detail: the alarm handler starts up in order, from ALM1 to ALM2. And the start-up sequence is in reverse order, from ALM2 to ALM1, if started simultaneously.	kernel/tkernel/src/timer.c	82	
9	Add the initialize sequence of variable.	kernel/tkernel/src/deviceio.c kernel/tkernel/src/device.c	1137 539	
	Revise the bug. The bug detail: the task may return from function while in an	kernel/tkernel/src/memory.c	189	
	interrupt-disabled state, in knl_lmalloc() and tm_getline() functions.	lib/libtm/src/ tm_getline.c	40	
- 11	Revise the bug. The bug detail: output can not be executed with tm_putchar when big endian is used. Revise the problem. The problem detail: there are programs which execute 32-bit	lib/libtm/src/tm_putchar.c	26	
12	access to the variables of INT type (16-bit) with mov. I, etc.	kernel/sysdepend/cpu/h8s2212/cpu_support.S	27	(
13	Add reference declaration.  Revise the bug. The bug detail: if 1 is set to USE_OBJECT_NAME, warning is issued	kernel/sysinit/src/sysstartup.c kernel/tkernel/src/objname.c	144	
14	when compiling.	kernel/tkernel/src/objname.c	167	
	Revise the bug. The bug detail: if 0 is set to CHK_RSATR, warning is issued when compiling.	kernel/tkernel/src/mailbox.c kernel/tkernel/src/mempfix.c kernel/tkernel/src/mempool.c kernel/tkernel/src/messagebuf.c kernel/tkernel/src/messagebuf.c kernel/tkernel/src/mendezvous.c kernel/tkernel/src/rendezvous.c kernel/tkernel/src/task_manage.c kernel/tkernel/src/time_calls.c kernel/tkernel/src/time_calls.c	68 69 255 131 228 94 68 36 213 613	
10	Revise the bug. The bug detail: if 0 is set to USE CLEANUP, error occurs when compiling.	kernel/sysinit/src/sysstartup.c kernel/sysinit/src/sysinit_main.c	93 20	
17	Revise the bug.	kernel/sysinit/src/sysstartup.c	47	
18	The bug detail: if 0 is set to USE IMALLOC, error occurs when compiling.  Revise the bug.  The bug detail: if 0 is set to USE_DBGSPT, error occurs when compiling by adding USE_TRAP option.	<pre>config/utk_config_func.h kernel/sysdepend/device/app_h8s2212/inthdr_startup.S Kernel/sysdepend/device/app_h8s2212/vector.S kernel/sysdepend/cpu/at91/cpu_support.S kernel/sysdepend/cpu/h8s2212/cpu_support.S</pre>	372 39	
19	Revise the bug. The bug detail: if 1 is set to USE_DBGSPT and 0 is set to USE_FUNC_TD_INF_TSK, error occurs when compiling.	kernel/tkernel/src/task.c	105	
	Revise the inappropriate comment, the function name, and the variable name in program to the appropriate ones.	include/tk/sysdepend/app_h8s2212/syslib_depend.h kernel/sysdepend/cpu/h8s2212/cpu_insn.h kernel/sysdepend/cpu/h8s2212/cpu_status.h kernel/sysdepend/cpu/h8s2212/cpu_support.S kernel/sysdepend/cpu/h8s2212/cpu_task.h		1
21	Revise redundant cast.	kernel/tkernel/src/rendezvous.h	68	
22	Delete redundant detection processing.	kernel/tkernel/src/mailbox.c kernel/sysdepend/cpu/h8s2212/cpu_calls.c	366 138	
23	Revise the bug regarding an output processing of mktksvc.	etc/mktksvc etc/mkiflib lib/libsvc/build/h8s2212/makeifex.pl		
	Revise the bug regarding an output processing of mktdsvc.	etc/mktdsvc		
	Revise Typo of label name.	kernel/sysdepend/device/app_at91/icrt0.\$	87	
	Delete unused variables.	kernel/sysdepend/device/app_h8s2212/tkdev_init.c	25 401	
	Revise the variable name.  Revise the bug regarding SIO processing.	kernel/tkernel/src/semaphore.c include/tk/sysdepend/app_h8s2212/sysdef_depend.h kernel/sysdepend/device/app_h8s2212/icrt0.S kernel/sysdepend/device/app_h8s2212/tkdev_timer.h lib/libtim/src/sysdepend/app_h8s2212/sio.c	93	

3. Quality improvements									
No.	Details	Subject source code	Line	No.					
1	Revise comments.	config/sysdepend/app_h8s2212/utk_config_depend.h kernel/sysdepend/cpu/at91/cpu_aupport.S kernel/sysdepend/device/app_at91/iort0.S kernel/tkernel/src/functions.list kernel/tkernel/src/check.h include/tk/sysdepend/app_at91/asm_depend.h include/tk/sysdepend/app_at91/cpudef.h include/tk/sysdepend/app_at91/dbgspt_depend.h include/tk/sysdepend/app_at91/sysdef_depend.h include/tk/sysdepend/app_at91/syslib_depend.h include/tk/sysdepend/app_at91/syslib_depend.h include/sys/svc/tdfncd.h lib/libsvc/src/sysdepend/include/tdfncd.h	97 65 109 253 18 18 18 18 18 11 1	1 4 1 1 1 1 1 1 1 1					
2	Revise comments.	kernel/tkernel/src/task.h	74	1					
3	Change the default value of TETYPE.	etc/makerules	43	1					
4	Change variable knl_taskindp to INT type.	include/sys/sysdepend/app_h8s2212/sysinfo_depend.h kernel/sysdepend/cpu/h8s2212/cpu_insn.h kernel/sysdepend/cpu/h8s2212/cpu_init.c kernel/sysdepend/cpu/h8s2212/cpu_support.S	36 25 26	1 1 1 4					

<sup># 1</sup> Although utkernel\_source/ is included at the beginning of each directory name in an archive, this has been omitted because it is common to all files.

<sup># 2 &</sup>quot;Line" refers to the line number in micro T-Kernel Version 1.01.00.
When a change covers multiple lines, only the first line number is indicated.
When a change spreads across different lines, the field is left blank.

 $<sup>\#\ 3</sup>$  The column of "No." (on the extreme right) is left blank when the number of changes is too great.