



QUALIMAX SERVICES



DETAILED WIND TURBINE BLADE INSPECTION REPORT

2026

- | | |
|--------------------------|----------------|
| ◦ CLIENT | - ALERION |
| ◦ PARK | - WIND PARK D |
| ◦ TURBINE NUMBER | - 1470026 |
| ◦ MODEL | - G52 (VESTAS) |
| ◦ INSPECTION DATE | - 12 FEB 2026 |

01	introduction	02
02	Blade A	
	Blade A - Overview	04
	Blade A - Annotation Details	05
03	Blade B	
	Blade B - Overview	08
	Blade B - Annotation Details	09
04	Blade C	
	Blade C - Overview	13
	Blade C - Annotation Details	14

Inspection Details


Turbine	Details
Wind Farm Name	Wind Park D
WTG Number	1470026
WTG Model	G52 (Vestas)
Customer	Vestas
Location	Spain
Report Number	IV-120226-004
Inspection Date	10 February 2026
Report date	12 February 2026

General Turbine Overview

Severity	Blade A	Blade B	Blade C
1	0	0	0
2	2	2	3
3	1	2	1
4	0	0	0
5	0	0	0
Total	3	4	4

Severity	Description	
1	Cosmetic	No intervention or immediate action is required
2	Minor	Repair only if other damages require repair
3	Medium	Repair within 5–6 months.
4	Serious	Repair within 2–3 months.
5	Critical	Immediate corrective action is required to prevent further turbine damage.


Blade A Overview



Damage ID	Blade side	Material	Damage Type	Subtype	Severity
120DA01	LE	Auxiliary Component	LEP	Damaged	2
120DA02	LE	Auxiliary Component	LEP	Peeling	2
120DA03	SS	Auxiliary Component	Drainage System	Damaged or Obstructed	3

Blade A


Damage 1



Blade	A
Side	Leading Edge
Material	Auxiliary Component
Type	Leading Edge Protection
Subtype	Damaged
Severity	2

Blade A


Damage 2



Blade	A
Side	Leading Edge
Material	Auxiliary Component
Type	Leading Edge Protection
Subtype	Peeling
Severity	2


Blade A

Damage 3



Blade	A
Side	Suction Side
Material	Auxiliary Component
Type	Drainage System
Subtype	Damaged or Obstructed
Severity	3


Blade B Overview



Damage ID	Blade side	Material	Damage Type	Subtype	Severity
120DB01	LE	Auxiliary Component	LEP	Damaged	2
120DB02	LE	Auxiliary Component	LEP	Peeling	2
120DB03	PS	Laminate	Delamination	none	3
120DB04	SS	Auxiliary Component	Drainage System	Damaged or Obstructed	3

Blade B

Damage 1



Blade	B
Side	Leading Edge
Material	Auxiliary Component
Type	Leading Edge Protection
Subtype	Damaged
Severity	2

Blade B

Damage 2



Blade	B
Side	Leading Edge
Material	Auxiliary Component
Type	Leading Edge Protection
Subtype	Peeling
Severity	2

Blade B


Damage 3



Blade	B
Side	Pressure Side
Material	Laminate
Type	Delamination
Subtype	none
Severity	3


Blade B

Damage 4



Blade	B
Side	Leading Edge
Material	Auxiliary Component
Type	Drainage System
Subtype	Damaged or Obstructed
Severity	3


Blade C Overview



Damage ID	Blade side	Material	Damage Type	Subtype	Severity
120DC01	LE	Auxiliary Component	LEP	Damaged	2
120DC02	LE	Auxiliary Component	LEP	Peeling	2
120DC03	PS	Auxiliary Component	LEP	Peeling	2
120DC04	SS	Auxiliary Component	Drainage System	Damaged or Obstructed	3

Blade C


Damage 1



Blade	C
Side	Leading Edge
Material	Auxiliary Component
Type	Leading Edge Protection
Subtype	Damaged
Severity	2

Blade C


Damage 2



Blade	C
Side	Leading Edge
Material	Auxiliary Component
Type	Leading Edge Protection
Subtype	Peeling
Severity	2

Blade C


Damage 3



Blade	C
Side	Leading Edge
Material	Auxiliary Component
Type	Leading Edge Protection
Subtype	Peeling
Severity	2

Blade C

Damage 4



Blade	C
Side	Leading Edge
Material	Auxiliary Component
Type	Drainage System
Subtype	Damaged or Obstructed
Severity	3

KEEP YOUR BLADES SAFER WITH...

**QUALIMAX
SERVICES**



www.qmservice.in