## Iteration 4: Homework 4

- Fill out the Default command
  - It should clear all the Params
  - Don't forget to call the Observers
- Add a shorthand to Param\_Get
  - o When the upper byte is zero, just send one byte