Delta Audit | New Findings Only

Differences found beyond the original Report_audit.pdf

This report does not repeat the original PDF's findings about general weak credentials, single points of failure, broad ACLs, FTP risk, basic logging, or incomplete AAA. It focuses on additional configuration-specific gaps from the teammate report.

NEW SEVERITY

4

Critical findings that were not fully captured in the original PDF.

MAIN THEME

Drift

Documentation and configuration do not always match.

ACTION

Fix

Apply and test controls before claiming compliance.

MOST IMPORTANT DELTA

Segmentation may be bypassed.
If PC default gateways are wrong, department ACLs do not protect traffic as intended.

CONTROL DRIFT

Claimed controls may not exist.
CoPP and VLAN 40 ACL are examples where definition is not the same as active enforcement.

AUDIT IMPACT

Score must drop.
These deltas move the report from moderate risk to high risk.

Not Repeated From Original PDF

ORIGINAL POINT	HOW THIS DELTA REPORT TREATS IT
Weak credentials in general	Not repeated, except where the teammate found a new specific authentication failure.
Broad ACLs in general	Not repeated, except where a specific ACL is missing, misordered, or dangerously broad.
Single core / edge router	Not repeated; already covered in Report_audit.pdf.
FTP weak users	Not repeated; already covered in Report_audit.pdf.
AAA not fully proven	Not repeated; this report only adds specific VTY/SSH/RADIUS-secret findings.

Delta conclusion: the teammate report adds implementation-level proof gaps. These are more serious than design weaknesses because they mean a control may look good on paper while failing in practice.

Critical Findings Added By Teammate Report

ID	NEW FINDING	WHY IT IS DIFFERENT FROM ORIGINAL PDF	NIST MAPPING	STATUS
D-01	SSH version 1 on ROUTER A	The original report said SSH exists; this finding says the router may use obsolete SSHv1, which is not acceptable.	IA-2, SC-8, SC-23	Critical
D-02	No VTY authentication on L2 switches	The original report discussed weak passwords; this is worse because remote access may require no valid credentials.	IA-2, AC-3, AC-17	Critical
D-03	Trivial plaintext enable password 0000	The original report covered weak credentials generally; this adds a specific privileged-mode failure on L3 core and DMZ switch.	IA-5, CM-6	Critical
D-04	Incorrect default gateways on VLAN 20/30/40 PCs	This is a new architecture-breaking issue: traffic may bypass VLAN-specific ACLs completely.	SC-7, AC-4, CM-6	Critical

Critical Remediation Commands / Actions

ACTION	EXPECTED CORRECTION
Force SSHv2 on Router A	`no ip ssh version 1`, then `ip ssh version 2`.
Fix VTY authentication	Create local admin, use `login local`, and restrict VTY to SSH.
Replace plaintext enable password	Remove `enable password`, configure `enable secret`.
Correct PC gateways	VLAN 20 to .33, VLAN 30 to .65, VLAN 40 to .97, preferably via DHCP.

High Findings Not Listed As Such In Original PDF

ID	FINDING	BUSINESS MEANING	NIST MAPPING	RISK
D-05	CoPP declared active but not attached	Control-plane DoS protection is claimed but not enforced.	SC-5, CM-7, CA-7	High
D-06	VLAN 40 ACL defined but not applied	Support B traffic may have no active access control.	AC-3, AC-4, SC-7	High
D-07	No ACL on VLAN 99 management	Internal hosts may reach administration infrastructure.	AC-3, MA-4, SC-7	High
D-08	No ACL on VLAN 50 printers	Printer/MFD devices may freely communicate across segments.	SC-7, CM-7, SI-3	High
D-09	Conflicting default routes on L3 core	Routing instability or packet loss could break services.	SC-7, CP-10, SI-2	High
D-10	DMZ ACL established rule before deny rules	DMZ flows may be allowed before intended isolation rules are evaluated.	AC-4, SC-7	High
D-11	UDP any/any in Production ACL	A broad early permit undermines the intended department isolation.	AC-4, CM-7	High
D-12	Internet DNS rule too broad	DNS traffic can become a command-and-control or exfiltration path.	SC-7, SC-20	High
D-13	L3-core SSH may be non-functional	Transport input ssh is not enough if RSA keys or SSHv2 are missing.	IA-2, SC-8	High

Additional Differences

ID	FINDING	WHY IT MATTERS	RISK
D-14	VLAN 99 IP conflict on Switch-L2-C and L2-D	Duplicate management IP can cause unstable administration and inventory confusion.	Medium
D-15	Empty RIP process on Router A	Unnecessary routing protocol configuration increases attack surface.	Medium
D-16	Orphan ACL sl_def_acl never applied	Unused and contradictory ACLs create false assurance and operational confusion.	Medium
D-17	Router console without local authentication	Console access should still enforce named-account accountability.	Medium
D-18	Port security absent on Switch-L2-D	One access switch lacks the endpoint controls present elsewhere.	Medium
D-19	NAT ACL covers the whole /24	Too broad compared with the documented /27 subnet plan.	Medium
D-20	DMZ switch syslog also points to wrong IP	Audit records may be sent to the wrong destination.	Medium
D-21	Most PCs use external DNS 8.8.8.8	Internal names may fail and DNS visibility moves outside the organization.	Medium
D-22	STP priority only configured for VLAN 10	Other VLANs may have less predictable spanning-tree behavior.	Medium
D-23	Unidentified DHCP devices	Unknown endpoints weaken asset inventory.	Low
D-24	Missing log keyword on ACL denies	Blocked traffic is harder to investigate.	Low

Impact On Final Audit Position

AREA	ORIGINAL PDF POSITION	DELTA ADJUSTMENT	NEW POSITION
Segmentation	Good design with ACLs to verify	Wrong gateways and missing VLAN 40 ACL may bypass it	Critical
Device management	SSH/AAA attempts, weak credentials	Possible no VTY auth and SSHv1	Critical
Control reliability	Evidence limitations noted	Specific claims do not match configs	High
Compliance score	67/100 moderate risk	New critical evidence reduces confidence	25-30%

Final delta statement: the second report does not merely add more findings. It changes the audit conclusion because it identifies control failure and documentation drift. The final defensible rating should therefore be high risk until the critical deltas are fixed and retested.