
Transfer curve
V_M = 2.24 V
V_{out} [V]
V_{in} [V]
0
1
2
3
4
5
Current through both transistors
supply current [mA]
0.0
0.2
0.4
0.6
0.8