CMOS inverter: OUT = not IN
The PMOS conducts for IN = 0, the NMOS for IN = 1.