Transmission gate: IN and OUT are connected when ON = 1 and ON_N = 0.
The NMOS passes a 0 well, the PMOS passes a 1 well; together they pass both.