




Support information

Brew Station TDS chart




Mineral Dosing (mL/L)	1.5	2.0	2.5	3.0	3.5	4.0	4.5
TDS	65	85	110	135	160	185	210
Acceptance +/-10 ppm	55-75	75-95	100-120	125-145	150-170	175-195	200-220

Measure TDS by following these steps

- Use a high quality TDS meter and check if it is on 0.5 or 0.7 conversion factor (Google the question and model name)
- Sample cold water from a Bluewater faucet or direct from tank
- Never sample water from a heated tank
- Flush 1 litre and discard
- Pour 1 litre and measure
- Change setting if wanted and repeat flushing and measuring



Support information



TDS Meter protocol

Measuring TDS is a way to understand how much Total Dissolved Solids are in the water. There are many meters on the market that does this and the accuracy is vastly inconsistent and should be of concern when buying a meter. Below is a study done in our lab, comparing 3 different TDS meters from expensive to cheap. It illustrates how cheaper meters aren't sensitive enough to detect all particles.

For us to fully support with faulty TDS claims, we preferably require that you invest in a high quality TDS meter and perform testing as described. A semi-accurate way is to test TDS with your current meter and send us the RO (zero minerals) number and the 4,5 mL/L number. We will send you a theoretical chart for your meter as a guide.

