

Aviation Investigation Final Report

Location: Gainesville, Florida Accident Number: GAA18CA243

Date & Time: April 29, 2018, 21:30 Local Registration: N2212A

Aircraft: Cessna 310 Aircraft Damage: Substantial

Defining Event: Controlled flight into terr/obj (CFIT) **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, on final approach at night, while speaking with the control tower, the airplane's left horizontal stabilizer struck a tree. The pilot added full power, pitched up, the airplane yawed left, and he resumed final approach. The airplane landed without further incident.

The airplane sustained substantial damage to the left horizontal stabilizer.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain an adequate approach path at night, which resulted in a tree strike.

Findings

Aircraft Descent/approach/glide path - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Tree(s) - Contributed to outcome

Environmental issues Dark - Effect on operation

Page 2 of 5 GAA18CA243

Factual Information

History of Flight

Approach-VFR pattern final Controlled flight into terr/obj (CFIT) (Defining event)	
Approach	Attempted remediation/recovery

Pilot Information

Certificate:	Private	Age:	30,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	May 15, 2014
Occupational Pilot:	No	Last Flight Review or Equivalent:	July 12, 2017
Flight Time:	(Estimated) 207.3 hours (Total, all aircraft), 67.3 hours (Total, this make and model), 115.3 hours (Pilot In Command, all aircraft), 19 hours (Last 90 days, all aircraft), 7.3 hours (Last 30 days, all aircraft), 1.5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2212A
Model/Series:	310 G	Aircraft Category:	Airplane
Year of Manufacture:	1962	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	310G-0018
Landing Gear Type:	Retractable - Tricycle	Seats:	5
Date/Type of Last Inspection:	March 21, 2018 Annual	Certified Max Gross Wt.:	4990 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:	3193.5 Hrs as of last inspection	Engine Manufacturer:	CONT MOTOR
ELT:	Installed, not activated	Engine Model/Series:	IO-470-D
Registered Owner:		Rated Power:	260 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA243

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KGNV,123 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	00:53 Local	Direction from Accident Site:	321°
Lowest Cloud Condition:	Few / 8500 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	80°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.1 inches Hg	Temperature/Dew Point:	23°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	PERRY, GA (PXE)	Type of Flight Plan Filed:	None
Destination:	FORT LAUDERDALE, FL (FXE)	Type of Clearance:	VFR;VFR flight following
Departure Time:	19:45 Local	Type of Airspace:	Class D

Airport Information

Airport:	GAINESVILLE RGNL GNV	Runway Surface Type:	Asphalt
Airport Elevation:	151 ft msl	Runway Surface Condition:	Dry
Runway Used:	11	IFR Approach:	None
Runway Length/Width:	7504 ft / 150 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	29.689167,-82.27333(est)

Page 4 of 5 GAA18CA243

Administrative Information

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Andrew W Crossman; FAA; Orlando, FL

Original Publish Date: August 27, 2018

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=97139

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA18CA243