



Aviation Investigation Final Report

Location: Talkeetna, Alaska Accident Number: GAA18CA535

Date & Time: September 4, 2018, 16:00 Local Registration: N7690H

Aircraft: Piper PA 12 Aircraft Damage: Substantial

Defining Event: Nose over/nose down **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, while landing uphill at an off-airport unimproved landing site where he had landed before, he applied the brakes, and that the airplane then hit a "bush or a bump," which caused the tail to rise. Subsequently, the propeller struck the ground, and the airplane nosed over.

The airplane sustained substantial damage to the empennage, fuselage, and wing spars.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain pitch control on uneven terrain during the landing roll, which resulted in a nose-over.

Findings

Personnel issues Aircraft control - Pilot

Aircraft Pitch control - Not attained/maintained

Environmental issues Mountainous/hilly terrain - Effect on operation

Page 2 of 5 GAA18CA535

Factual Information

History of Flight

Landing	Collision with terr/obj (non-CFIT)
Landing	Nose over/nose down (Defining event)

Pilot Information

Certificate:	Private	Age:	37,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	5-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	April 14, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	November 12, 2016
Flight Time:	(Estimated) 242.8 hours (Total, all aircraft), 224.3 hours (Total, this make and model), 192.8 hours (Pilot In Command, all aircraft), 82 hours (Last 90 days, all aircraft), 28.2 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N7690H
Model/Series:	PA 12 No Series	Aircraft Category:	Airplane
Year of Manufacture:	1946	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	12-580
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	April 4, 2018 Annual	Certified Max Gross Wt.:	1933 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3715 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C126 installed, not activated	Engine Model/Series:	O-235-A2B
Registered Owner:		Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA535

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Day
PATK,356 ft msl	Distance from Accident Site:	40 Nautical Miles
23:53 Local	Direction from Accident Site:	259°
Few / 5000 ft AGL	Visibility	10 miles
	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	None / None
	Turbulence Severity Forecast/Actual:	N/A / N/A
30.23 inches Hg	Temperature/Dew Point:	15°C / 8°C
No Obscuration; No Precipitation		
Talkeetna, AK (TKA)	Type of Flight Plan Filed:	None
Talkeetna, AK	Type of Clearance:	VFR
	Type of Airspace:	Class G
	PATK,356 ft msl 23:53 Local Few / 5000 ft AGL / 30.23 inches Hg No Obscuration; No Precipital Talkeetna, AK (TKA)	PATK,356 ft msl Distance from Accident Site: 23:53 Local Direction from Accident Site: Few / 5000 ft AGL Visibility Visibility (RVR): / Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: 30.23 inches Hg Temperature/Dew Point: No Obscuration; No Precipitation Talkeetna, AK (TKA) Type of Flight Plan Filed: Type of Clearance:

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	62.452777,-148.68695(est)

Administrative Information

Investigator In Charge (IIC):	Swenson, Eric
Additional Participating Persons:	Shawn Gannon; FAA; Anchorage, AK
Original Publish Date:	March 18, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98246

Page 4 of 5 GAA18CA535

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA535