



Aviation Investigation Final Report

Location: Chicago, Illinois Accident Number: GAA18CA588

Date & Time: July 17, 2018, 09:20 Local Registration: N969RR

Aircraft: Cessna 172 Aircraft Damage: Substantial

Defining Event: Ground collision **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The solo student pilot reported that, during taxi to the runway, he saw a fuel truck parked in the grass on the left side of the asphalt taxilane. He added that he "assumed that the truck driver had left room for airplanes to get by"; however, as the airplane passed the truck, its left wing struck the rear of the truck.

The airplane sustained substantial damage to the left wing lift strut.

The student reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's failure to maintain clearance from a truck while taxiing.

Findings

Personnel issues Monitoring environment - Student/instructed pilot

Environmental issues Ground vehicle - Effect on operation

Factual Information

History of Flight

Taxi-to runway	Ground collision (Defining event)	
----------------	-----------------------------------	--

Pilot Information

Certificate:	Student	Age:	53,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	March 31, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 28.2 hours (Total, all aircraft), 28.2 hours (Total, this make and model), 0.4 hours (Pilot In Command, all aircraft), 20.2 hours (Last 90 days, all aircraft), 4.9 hours (Last 30 days, all aircraft), 0.8 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N969RR
Model/Series:	172 P	Aircraft Category:	Airplane
Year of Manufacture:	1982	Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	17275850
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed	Engine Model/Series:	0-320
Registered Owner:		Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None

Page 2 of 4 GAA18CA588

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KPWK,636 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	04:52 Local	Direction from Accident Site:	340°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	23°C / 14°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Chicago, IL (PWK)	Type of Flight Plan Filed:	None
Destination:	Chicago, IL (PWK)	Type of Clearance:	None
Departure Time:	10:00 Local	Type of Airspace:	Class D

Airport Information

Airport:	Chicago Executive PWK	Runway Surface Type:	Asphalt
Airport Elevation:	646 ft msl	Runway Surface Condition:	Dry
Runway Used:		IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	42.114166,-87.901664(est)

Page 3 of 4 GAA18CA588

Administrative Information

Investigator In Charge (IIC): Hicks, Michael

Additional Participating Persons: James Lobash; FAA; DuPage, IL

Original Publish Date: September 26, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=99311

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 4 of 4 GAA18CA588