



# **Aviation Investigation Final Report**

Location: Benson, Arizona Accident Number: GAA19CA072

Date & Time: November 23, 2018, 08:30 Local Registration: N50340

Aircraft: BELLANCA 7GCBC Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot of the tailwheel-equipped airplane reported that, during the landing, the right wing lifted, and the airplane drifted left. He added that he "overcorrected," and the airplane veered right off the runway. The left main landing gear caught in the dirt and collapsed, and the left wing impacted the ground.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The pilot reported that, about 15 minutes before the accident, the wind conditions were variable and calm.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's overcorrection during the landing, which resulted in a loss of directional control.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Aircraft Rudder control system - Incorrect use/operation

Personnel issues Use of equip/system - Pilot

**Environmental issues** Crosswind - Effect on operation

**Environmental issues** Soft surface - Contributed to outcome

Page 2 of 5 GAA19CA072

## **Factual Information**

## **History of Flight**

Landing	Loss of control on ground (Defining event)
Landing	Attempted remediation/recovery
Landing	Runway excursion
Landing	Landing gear collapse
Landing	Collision with terr/obj (non-CFIT)

#### **Pilot Information**

Certificate:	Private	Age:	51,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	January 25, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	March 3, 2018
Flight Time:	(Estimated) 118.3 hours (Total, all aircraft), 19.1 hours (Total, this make and model), 53.9 hours (Pilot In Command, all aircraft), 4.4 hours (Last 90 days, all aircraft)		

Page 3 of 5 GAA19CA072

### Aircraft and Owner/Operator Information

BELLANCA	Registration:	N50340
7GCBC	Aircraft Category:	Airplane
1978	Amateur Built:	
Aerobatic; Normal	Serial Number:	1074-79
Tailwheel	Seats:	2
Unknown	Certified Max Gross Wt.:	
	Engines:	1 Reciprocating
	Engine Manufacturer:	Lycoming
	Engine Model/Series:	0-320
	Rated Power:	
On file	Operating Certificate(s) Held:	None
	7GCBC 1978 Aerobatic; Normal Tailwheel Unknown	7GCBC Aircraft Category:  1978 Amateur Built:  Aerobatic; Normal Serial Number:  Tailwheel Seats:  Unknown Certified Max Gross Wt.:  Engines:  Engine Manufacturer:  Engine Model/Series:  Rated Power:  On file Operating Certificate(s)

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KTUS,2555 ft msl	Distance from Accident Site:	32 Nautical Miles
Observation Time:	15:53 Local	Direction from Accident Site:	285°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	110°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.2 inches Hg	Temperature/Dew Point:	10°C / 3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Benson, AZ (E95)	Type of Flight Plan Filed:	None
Destination:	Benson, AZ (E95)	Type of Clearance:	None
Departure Time:	08:15 Local	Type of Airspace:	Class G

Page 4 of 5 GAA19CA072

#### **Airport Information**

Airport:	BENSON MUNI E95	Runway Surface Type:	Asphalt
Airport Elevation:	3830 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	28	IFR Approach:	None
Runway Length/Width:	4002 ft / 75 ft	VFR Approach/Landing:	Full stop;Stop and go:Traffic pattern

#### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	31.999166,-110.355834(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Benhoff, Kathryn
Additional Participating Persons:	Daniel Gredlein; FAA; Scottsdale, AZ
Original Publish Date:	September 26, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=98677

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA19CA072