



Aviation Investigation Final Report

Location: Logandale, Nevada Accident Number: GAA19CA256

Date & Time: May 10, 2019, 11:30 Local Registration: N776RT

Aircraft: Jordan Valley Llc CCX-2000 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, during landing on a gravel airstrip, the airplane veered left. He started to go around, but the airplane continued left toward trees. To avoid the trees, he banked the airplane to the right, the right wing struck the ground, and the airplane cartwheeled and then came to rest on its landing gear.

The airplane sustained substantial damage to the left wing and fuselage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing and during a subsequent attempted goaround, which resulted in the airplane cartwheeling.

Findings

A ! £4	Discretional control Not attained (sectional)
Aircraft	Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 5 GAA19CA256

Factual Information

History of Flight

Landing	Loss of control on ground
J	•
Landing-aborted after touchdown	Loss of control on ground (Defining event)
Landing-aborted after touchdown	Collision with terr/obj (non-CFIT)

Pilot Information

Certificate:	Private	Age:	66,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	November 8, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	April 22, 2018
Flight Time:	(Estimated) 1340 hours (Total, all aircraft), 98 hours (Total, this make and model), 1340 hours (Pilot In Command, all aircraft), 107 hours (Last 90 days, all aircraft), 41 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA19CA256

Aircraft and Owner/Operator Information

Aircraft Make:	Jordan Valley Llc	Registration:	N776RT
Model/Series:	CCX-2000 FX 3	Aircraft Category:	Airplane
Year of Manufacture:	2018	Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	CCX2000-0034
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	November 13, 2018 Unknown	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	145 Hrs as of last inspection	Engine Manufacturer:	Superior
ELT:	C126 installed, not activated	Engine Model/Series:	CC363i
Registered Owner:		Rated Power:	186 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KBVU,2202 ft msl	Distance from Accident Site:	38 Nautical Miles
Observation Time:	19:35 Local	Direction from Accident Site:	243°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots / 13 knots	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	40°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.85 inches Hg	Temperature/Dew Point:	20°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Overton, NV (U08)	Type of Flight Plan Filed:	None
Destination:	Logandale, NV	Type of Clearance:	None
Departure Time:	11:00 Local	Type of Airspace:	Class G

Page 4 of 5 GAA19CA256

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	36.240833,-114.175003(est)

Administrative Information

Investigator In Charge (IIC): Gutierrez, Eric

Additional Participating Persons: Carey Atnip; FAA; Las Vegas, NV

Original Publish Date: March 3, 2020

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=99415

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA19CA256