



Aviation Investigation Final Report

Location: Rolla, Missouri Accident Number: GAA19CA008

Date & Time: October 8, 2018, 17:38 Local Registration: N685JM

Aircraft: Cessna 188 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 Minor

Flight Conducted Under: Part 137: Agricultural

Analysis

The pilot of the tailwheel-equipped airplane reported that, during takeoff, the airplane veered left, exited the runway, and impacted trees.

The airplane sustained substantial damage to the left wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

According to a Federal Aviation Administration inspector, the pilot did not have a current biannual flight review nor a current medical certificate, and the airplane was not airworthy.

The pilot stated that, during takeoff, the wind was gusting. The automated weather observation station located about 12 nautical miles from the airport reported that, about the time of the accident, the wind was from 140° at 7 knots. The airplane departed from runway 27.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during takeoff in a left quartering tailwind.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issuesTailwind - Effect on operationEnvironmental issuesTree(s) - Contributed to outcome

Page 2 of 5 GAA19CA008

Factual Information

History of Flight

Takeoff	Loss of control on ground (Defining event)		
Takeoff	Runway excursion		
Takeoff	Collision with terr/obj (non-CFIT)		

Pilot Information

Certificate:	Commercial	Age:	67,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Single
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Without waivers/limitations	Last FAA Medical Exam:	May 1, 1999
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	(Estimated)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N685JM
Model/Series:	188 B	Aircraft Category:	Airplane
Year of Manufacture:	1974	Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18801992
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Continental
ELT:		Engine Model/Series:	O-470 SERIES
Registered Owner:		Rated Power:	
Operator:		Operating Certificate(s) Held:	Agricultural aircraft (137)

Page 3 of 5 GAA19CA008

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Conditions at Accident Site.	visual (vivic)	Condition of Light.	Day
Observation Facility, Elevation:	KVIH,1110 ft msl	Distance from Accident Site:	12 Nautical Miles
Observation Time:	22:53 Local	Direction from Accident Site:	11°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	140°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.97 inches Hg	Temperature/Dew Point:	26°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Rolla, MO (K07)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	ROLLA DOWNTOWN K07	Runway Surface Type:	Asphalt
Airport Elevation:	987 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	3028 ft / 38 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	37.935554,-91.813613(est)

Page 4 of 5 GAA19CA008

Administrative Information

Investigator In Charge (IIC):

Additional Participating Persons:
Randy Ottinger; FAA; St. Louis, MO
Dennis Mueller; FAA; St. Louis, MO

Original Publish Date:
June 10, 2019

This accident report documents the factual circumstances of this accident as described to the NTSB.

Investigation Docket:
https://data.ntsb.gov/Docket?ProjectID=98431

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA19CA008