



# **Aviation Investigation Final Report**

Location: Warren, Arkansas Accident Number: GAA18CA442

Date & Time: July 14, 2018, 11:30 Local Registration: N2127C

Aircraft: Champion 7GC Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that, during a three-point landing in a tailwheel-equipped airplane, as soon as the airplane touched down, the tailwheel shimmied. He raised the tail attempting to keep the airplane straight, but it veered right. He applied left brake, but the airplane continued toward a ditch. He then applied right rudder and right brake attempting to spin the airplane.

The airplane sustained substantial damage to the left wing and left elevator.

The pilot reported that the wind was from 230° at 4 knots at the accident airport. The automated weather observation system about 17 nautical miles from the accident site reported that, about the time of the accident, the wind was from 230° at 7 knots. The pilot landed the airplane on runway 21.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during landing.

## Findings

A ! £4	Discretional control Not attained (sectional)
Aircraft	Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Page 2 of 5 GAA18CA442

## **Factual Information**

## **History of Flight**

Landing	Abnormal runway contact
Landing	Loss of control on ground (Defining event)

#### **Pilot Information**

Certificate:	Private	Age:	24,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	August 7, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	August 12, 2018
Flight Time:	(Estimated) 290 hours (Total, all aircraft), 150 hours (Total, this make and model), 290 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Champion	Registration:	N2127C
Model/Series:	7GC No Series	Aircraft Category:	Airplane
Year of Manufacture:	1959	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7GC-50
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	July 11, 2018 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2426 Hrs at time of accident	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	O-290-D2B
Registered Owner:		Rated Power:	140 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA442

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KLLQ,270 ft msl	Distance from Accident Site:	17 Nautical Miles
Observation Time:	16:53 Local	Direction from Accident Site:	75°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.09 inches Hg	Temperature/Dew Point:	33°C / 26°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Carlisle, AR (4M3)	Type of Flight Plan Filed:	None
Destination:	Warren, AR (3M9)	Type of Clearance:	None
Departure Time:	10:45 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	Warren Muni 3M9	Runway Surface Type:	Asphalt
Airport Elevation:	235 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	21	IFR Approach:	None
Runway Length/Width:	3829 ft / 75 ft	VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.564445,-92.081108(est)

Page 4 of 5 GAA18CA442

#### **Administrative Information**

Investigator In Charge (IIC): Swenson, Eric

Additional Participating Persons: Shane Benedetto; FAA; Little Rock, AR

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=97899">https://data.ntsb.gov/Docket?ProjectID=97899</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA18CA442