



Aviation Investigation Final Report

Location: Kake, Alaska Accident Number: GAA18CA310

Date & Time: May 30, 2018, 09:14 Local Registration: N2716X

Aircraft: Cessna 180 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel-equipped airplane reported that, while taxiing from the runway in crosswind conditions, he "failed to maintain directional control." Subsequently, the airplane ground looped counterclockwise.

The airplane sustained substantial damage to the left wing and elevator.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

The automated weather observation system at the airport reported that, about the time of the accident, the wind was from 230° at 4 knots. The pilot landed on runway 29.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control while exiting the runway after landing.

Findings

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Environmental issues Crosswind - Effect on operation

Page 2 of 5 GAA18CA310

Factual Information

History of Flight

Taxi-from runway	Loss of control on ground (Defining event)	
------------------	--	--

Pilot Information

Private	Age:	39,Male
Single-engine land; Single-engine sea	Seat Occupied:	Left
None	Restraint Used:	Unknown
Airplane	Second Pilot Present:	No
None	Toxicology Performed:	No
Class 3 Without waivers/limitations	Last FAA Medical Exam:	September 29, 2016
No	Last Flight Review or Equivalent:	August 8, 2017
(Estimated) 738.5 hours (Total, all aircraft), 192.2 hours (Total, this make and model), 695.4 hours (Pilot In Command, all aircraft), 31.7 hours (Last 90 days, all aircraft), 9.8 hours (Last 30 days, all aircraft), 3.2 hours (Last 24 hours, all aircraft)		
	Single-engine land; Single-engine sea None Airplane None Class 3 Without waivers/limitations No (Estimated) 738.5 hours (Total, all air (Pilot In Command, all aircraft), 31.7	Single-engine land; Single-engine sea None Restraint Used: Airplane Second Pilot Present: None Toxicology Performed: Class 3 Without waivers/limitations Last FAA Medical Exam: No Last Flight Review or Equivalent: (Estimated) 738.5 hours (Total, all aircraft), 192.2 hours (Total, this make a (Pilot In Command, all aircraft), 31.7 hours (Last 90 days, all aircraft), 9.8 hours

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2716X
Model/Series:	180 H	Aircraft Category:	Airplane
Year of Manufacture:	1965	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18051516
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	March 26, 2018 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	208.8 Hrs as of last inspection	Engine Manufacturer:	CONT MOTOR
ELT:	C126 installed, not activated	Engine Model/Series:	O-470 R
Registered Owner:		Rated Power:	230 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA310

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAFE,172 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	17:56 Local	Direction from Accident Site:	74°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:	Broken / 5000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.05 inches Hg	Temperature/Dew Point:	9°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	JUNEAU, AK (JNU)	Type of Flight Plan Filed:	VFR
Destination:	Kake, AK (AFE)	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Airport Information

Airport:	KAKE AFE	Runway Surface Type:	Asphalt
Airport Elevation:	171 ft msl	Runway Surface Condition:	Dry
Runway Used:	29	IFR Approach:	None
Runway Length/Width:	4000 ft / 100 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	56.964443,-133.915832(est)

Page 4 of 5 GAA18CA310

Administrative Information

Investigator In Charge (IIC): Swenson, Eric

Additional Participating Persons: Rich Peabody; FAA; Juneau, AK

Original Publish Date: November 5, 2018

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=97360

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 5 of 5 GAA18CA310