



Aviation Investigation Final Report

Location: Porterville, California **Accident Number:** GAA19CA073

Date & Time: November 25, 2018, 13:20 Local Registration: N66710

Aircraft: Beech C23 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot reported that, during the landing flare, the airplane touched down on the main landing gear and ballooned a few feet off the ground. Subsequently, the airplane porpoised, the nosewheel collapsed, and the airplane came to rest nose down on the runway.

The airplane sustained substantial damage to the engine mount.

The pilot reported that there were no preimpact mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare, which resulted in an abnormal landing and subsequent porpoise.

Findings

Aircraft Pitch control - Not attained/maintained

Personnel issues Aircraft control - Pilot

Factual Information

History of Flight

Abnormal runway contact
Loss of control on ground (Defining event)
Landing gear collapse
Nose over/nose down

Pilot Information

Certificate:	Private	Age:	71,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	March 7, 2018
Occupational Pilot:	No Last Flight Review or Equivalent: May 22, 2017		
Flight Time:	(Estimated) 242 hours (Total, all aircraft), 220 hours (Total, this make and model), 132 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Beech	Registration:	N66710
Model/Series:	C23	Aircraft Category:	Airplane
Year of Manufacture:	1983	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	M-2387
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	November 20, 2017 Annual	Certified Max Gross Wt.:	2450 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	6109 Hrs as of last inspection	Engine Manufacturer:	Lycoming
ELT:	C91 installed, not activated	Engine Model/Series:	0-360-A4K
Registered Owner:		Rated Power:	180 Horsepower
Operator:	On file	Operating Certificate(s) Held:	Fractional ownership

Page 2 of 4 GAA19CA073

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KPTV,442 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	21:56 Local	Direction from Accident Site:	177°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.05 inches Hg	Temperature/Dew Point:	21°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	Porterville, CA (PTV)	Type of Flight Plan Filed:	None
Destination:	Porterville, CA (PTV)	Type of Clearance:	None
Departure Time:	12:50 Local	Type of Airspace:	Class G

Airport Information

Airport:	PORTERVILLE MUNI PTV	Runway Surface Type:	Asphalt
Airport Elevation:	443 ft msl	Runway Surface Condition:	Dry
Runway Used:	30	IFR Approach:	None
Runway Length/Width:	5960 ft / 150 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	36.029998,-119.063056(est)

Page 3 of 4 GAA19CA073

Administrative Information

Investigator In Charge (IIC): Gutierrez, Eric

Additional Participating Persons: Troy Wise; FAA; Fresno, CA

Original Publish Date: September 26, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=98678

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available here.

Page 4 of 4 GAA19CA073