



Aviation Investigation Final Report

Location: Reedsburg, Wisconsin Accident Number: GAA19CA218

Date & Time: April 20, 2019, 14:52 Local Registration: N59DW

Aircraft: Cessna 180 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Aerial observation

Analysis

The pilot of the tailwheel-equipped airplane reported that, after a three-point landing, during the landing roll, the airplane veered left. He corrected with right rudder, but the airplane continued left, so he applied brakes, and the airplane nosed over.

The airplane sustained substantial damage to the right wing.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's loss of directional control and subsequent improper brake application during the landing roll, which resulted in a nose-over.

Findings

Aircraft Directional control - Not attained/maintained

Aircraft Brake - Incorrect use/operation

Personnel issues Aircraft control - Pilot

Personnel issues Use of equip/system - Pilot

Page 2 of 5 GAA19CA218

Factual Information

History of Flight

Landing-landing roll	Loss of control on ground (Defining event)	
Landing-landing roll	Attempted remediation/recovery	

Pilot Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	65,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 With waivers/limitations	Last FAA Medical Exam:	December 12, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	February 19, 2019
Flight Time:	(Estimated) 10289 hours (Total, all aircraft), 648 hours (Total, this make and model), 9943 hours (Pilot In Command, all aircraft), 47 hours (Last 90 days, all aircraft), 47 hours (Last 30 days, all aircraft), 7 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA19CA218

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N59DW
Model/Series:	180 J	Aircraft Category:	Airplane
Year of Manufacture:	1975	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052649
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	January 8, 2019 100 hour	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	8041.9 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	0-470-S
Registered Owner:		Rated Power:	230 Horsepower
Operator:		Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KDLL,976 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	04:35 Local	Direction from Accident Site:	91°
Lowest Cloud Condition:		Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.85 inches Hg	Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Necedah, WI (DAF)	Type of Flight Plan Filed:	None
Destination:	Reedsburg, WI (C35)	Type of Clearance:	None
Departure Time:	12:10 Local	Type of Airspace:	Class G

Page 4 of 5 GAA19CA218

Airport Information

Airport:	Reedsburg Muni C35	Runway Surface Type:	Asphalt
Airport Elevation:	906 ft msl	Runway Surface Condition:	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	4840 ft / 75 ft	VFR Approach/Landing:	Full stop:Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	43.525833,-89.983329(est)

Administrative Information

Investigator In Charge (IIC):	Nepomuceno, Eleazar
Additional Participating Persons:	Peter Hupfer; FAA; Milwaukee, WI
Original Publish Date:	March 3, 2020
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=99302

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA19CA218