



Aviation Investigation Final Report

Location: Yakutat, Alaska Accident Number: GAA16CA474

Date & Time: September 2, 2016, 17:00 Local Registration: N54AF

Aircraft: Cessna 180 Aircraft Damage: Substantial

Defining Event: Nose over/nose down **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel equipped airplane reported that during the landing roll on a grass field the airplane encountered standing water and nosed over.

The airplane sustained substantial damage to the left wing, the right wing strut, and the empennage.

The pilot reported that there were no preimpact mechanical failures or malfunctions with the airframe or engine that would have precluded normal operation.

The pilot reported as a safety recommendation to conduct a more thorough pre-landing reconnaissance of the intended landing zone.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate inspection of the off-airport landing area, which resulted in an encounter with standing water and a nose over.

Findings

Personnel issues Monitoring environment - Pilot

Environmental issues Water - Effect on operation

Factual Information

History of Flight

Landing-landing roll Nose over/nose down (Delining event)	Landing-landing roll	Nose over/nose down (Defining event)	
---	----------------------	--------------------------------------	--

Pilot Information

Certificate:	Airline transport; Commercial; Flight instructor	Age:	61,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 With waivers/limitations	Last FAA Medical Exam:	January 12, 2016
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	May 27, 2015
Flight Time:	(Estimated) 14300 hours (Total, all aircraft), 990 hours (Total, this make and model), 14209 hours (Pilot In Command, all aircraft), 68 hours (Last 90 days, all aircraft), 28.3 hours (Last 30 days, all aircraft)		

Page 2 of 4 GAA16CA474

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N54AF
Model/Series:	180 UNDESIGNAT	Aircraft Category:	Airplane
Year of Manufacture:	1954	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	30943
Landing Gear Type:	Tailwheel	Seats:	3
Date/Type of Last Inspection:	April 1, 2016 Annual	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3874.6 Hrs as of last inspection	Engine Manufacturer:	CONT MOTOR
ELT:	C91A installed, activated, did not aid in locating accident	Engine Model/Series:	10520ACC
Registered Owner:		Rated Power:	235 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAYA,31 ft msl	Distance from Accident Site:	24 Nautical Miles
Observation Time:	00:53 Local	Direction from Accident Site:	120°
Lowest Cloud Condition:	Few / 10000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	280°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.97 inches Hg	Temperature/Dew Point:	18°C / 7°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Yakutat, AK	Type of Flight Plan Filed:	None
Destination:	Yakutat, AK	Type of Clearance:	None
Departure Time:		Type of Airspace:	Class G

Page 3 of 4 GAA16CA474

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	59.712223,-140.348052(est)

Administrative Information

Investigator In Charge (IIC):Benhoff, KathrynAdditional Participating Persons:Tom Tilson; FAA; Juneau, AKOriginal Publish Date:December 5, 2016Note:This accident report documents the factual circumstances of this accident as described to the NTSB.Investigation Docket:https://data.ntsb.gov/Docket?ProjectID=93985

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 4 of 4 GAA16CA474