



Aviation Investigation Final Report

Location: Pullman, Washington Accident Number: GAA19CA159

Date & Time: March 9, 2019, 12:20 Local Registration: N4100Z

Aircraft: Piper PA18 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot of the tailwheel- and ski-equipped airplane reported that, while landing off airport on a snow-covered ridge, the back of the right ski struck about a 6-inch-tall, firm snow drift. The right ski then pitched forward, the tip dug into the "crusty" snow, and the airplane nosed over.

The airplane sustained substantial damage to the fuselage, empennage, and lift strut.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's selection of unsuitable terrain for landing, which resulted in a nose-over.

Findings

Personnel issues Decision making/judgment - Pilot
Environmental issues Snow/ice - Effect on operation

Environmental issues Snow/slush/ice covered surface - Effect on operation

Environmental issues Sloped/uneven terrain - Effect on operation

Page 2 of 5 GAA19CA159

Factual Information

History of Flight

Landing	Collision with terr/obj (non-CFIT)
Landing	Loss of control on ground (Defining event)
Landing	Nose over/nose down

Pilot Information

Certificate:	Private	Age:	63,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	4-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	July 25, 2017
Occupational Pilot:	No	Last Flight Review or Equivalent:	May 27, 2017
Flight Time:	(Estimated) 2379 hours (Total, all aircraft), 1268 hours (Total, this make and model), 2379 hours (Pilot In Command, all aircraft), 38 hours (Last 90 days, all aircraft), 21 hours (Last 30 days, all aircraft)		

Page 3 of 5 GAA19CA159

Aircraft and Owner/Operator Information

Aircraft Make:	Piper	Registration:	N4100Z
Model/Series:	PA18 150	Aircraft Category:	Airplane
Year of Manufacture:	1964	Amateur Built:	
Airworthiness Certificate:	Normal; Utility	Serial Number:	18-8114
Landing Gear Type:	Tailwheel; Ski/wheel	Seats:	2
Date/Type of Last Inspection:	July 20, 2018 Annual	Certified Max Gross Wt.:	2000 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	5459.45 Hrs	Engine Manufacturer:	Lycoming
ELT:	C126 installed, activated, did not aid in locating accident	Engine Model/Series:	O-320-B2B
Registered Owner:		Rated Power:	160 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KPUW,2551 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	11:53 Local	Direction from Accident Site:	300°
Lowest Cloud Condition:	Few / 2300 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.95 inches Hg	Temperature/Dew Point:	-9°C / -11°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Pullman/Moscow, WA (PUW)	Type of Flight Plan Filed:	None
Destination:	Pullman/Moscow, WA (PUW)	Type of Clearance:	None
Departure Time:	12:20 Local	Type of Airspace:	Class E

Page 4 of 5 GAA19CA159

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	46.735832,-117.088058(est)

Administrative Information

Investigator In Charge (IIC):Swenson, EricAdditional Participating Persons:Chris Lang; FAA; Spokane, WAOriginal Publish Date:November 6, 2019Note:This accident report documents the factual circumstances of this accident as described to the NTSB.Investigation Docket:https://data.ntsb.gov/Docket?ProjectID=99090

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA19CA159