

# **Aviation Investigation Final Report**

Location: Winchester, Virginia Accident Number: GAA16CA460

Date & Time: August 30, 2016, 12:30 Local Registration: N2462E

Aircraft: Cessna 172 Aircraft Damage: Substantial

**Defining Event:** Abnormal runway contact **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

The solo student pilot reported that the airplane ballooned during the landing flare and touched down beyond the planned touchdown point. He further reported that the airplane porpoised and on the third bounce he felt a vibration. Subsequently, the airplane departed the runway to the left and stopped in grass next to the runway.

The firewall sustained substantial damage.

The student pilot reported no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's incorrect pitch control during the landing flare, which resulted in a porpoise, a loss of directional control, and a runway excursion.

## **Findings**

Aircraft	Pitch control - Incorrect use/operation	
Personnel issues	Aircraft control - Student/instructed pilot	
Aircraft	Directional control - Not attained/maintained	

Page 2 of 5 GAA16CA460

## **Factual Information**

#### **History of Flight**

Landing-flare/touchdown Abnormal runway contact (Defining event)

Landing-landing roll Loss of control on ground

Landing-landing roll Runway excursion

**Landing-landing roll** Collision with terr/obj (non-CFIT)

#### **Student pilot Information**

Certificate:	Student	Age:	42,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	January 20, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	(Estimated) 66 hours (Total, all aircraft), 49 hours (Total, this make and model), 3 hours (Pilot In Command, all aircraft), 4 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA16CA460

## Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N2462E
Model/Series:	172 N	Aircraft Category:	Airplane
Year of Manufacture:	1978	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17271291
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	June 24, 2016 Annual	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	9923.2 Hrs at time of accident	Engine Manufacturer:	LYCOMING
ELT:	C91 installed, not activated	Engine Model/Series:	0-320-H2AD
Registered Owner:		Rated Power:	160 Horsepower
Operator:		Operating Certificate(s) Held:	None

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KOKV,726 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	16:35 Local	Direction from Accident Site:	0°
<b>Lowest Cloud Condition:</b>	Scattered / 5000 ft AGL	Visibility	10 miles
Lowest Ceiling:		Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/ None
Wind Direction:		Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.15 inches Hg	Temperature/Dew Point:	28°C / 15°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	MARTINSBURG, WV (MRB)	Type of Flight Plan Filed:	None
Destination:	Winchester, VA (OKV)	Type of Clearance:	VFR
Departure Time:	12:10 Local	Type of Airspace:	Class G

Page 4 of 5 GAA16CA460

#### **Airport Information**

Airport:	WINCHESTER RGNL OKV	Runway Surface Type:	Asphalt
Airport Elevation:	726 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	5498 ft / 100 ft	VFR Approach/Landing:	Stop and go;Traffic pattern

#### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.143611,-78.144447(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Gerhardt, Adam
Additional Participating Persons:	John Teehan; FAA; Dulles, VA
Original Publish Date:	December 5, 2016
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=93935

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA16CA460