











DCA19WA020



Aviation Investigation Preliminary Report

Location: **Accident Number:** Paris,

Date & Time: October 31, 2018, 09:44 UTC Registration: N817NW

Aircraft: Airbus A330 Injuries:

Flight Conducted Under: Part 121: Air carrier - Scheduled

Aircraft and Owner/Operator Information

Aircraft Make: Airbus Registration: N817NW

Model/Series: A330 323 **Aircraft Category:** Airplane

Amateur Built:

Operator: **Operating Certificate(s)** Flag carrier (121)

Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site: Condition of Light:

Observation Facility, Elevation: **Observation Time:**

Distance from Accident Site: Temperature/Dew Point:

Lowest Cloud Condition: Wind Speed/Gusts, Direction: /,

Lowest Ceiling: Visibility:

Type of Flight Plan Filed: **Altimeter Setting:**

Departure Point: Destination:

Wreckage and Impact Information

| Crew Injuries: | Aircraft Damage: | Minor |
|---------------------|----------------------|--------------------------|
| Passenger Injuries: | Aircraft Fire: | None |
| Ground Injuries: | Aircraft Explosion: | None |
| Total Injuries: | Latitude, Longitude: | 48.998889,2.560277 (est) |

Administrative Information

| Investigator In Charge (IIC): | Bower, Daniel |
|-----------------------------------|--|
| Additional Participating Persons: | |
| Note: | The NTSB did not travel to the scene of this accident. |

Page 2 of 4 DCA19WA020













Aviation Investigation Preliminary Report

Location: Paris, Accident Number: DCA19WA020

Date & Time: October 31, 2018, 09:44 UTC Registration: F-GZCI

Aircraft: Airbus A330 Injuries:

Flight Conducted Under: Non-U.S., commercial

Aircraft and Owner/Operator Information

Aircraft Make: Airbus Registration: F-GZCI

Model/Series: A330 200 Aircraft Category: Airplane

Amateur Built:

Operator: Operating Certificate(s)

Held:

Operator Designator Code:

Meteorological Information and Flight Plan

Conditions at Accident Site: Condition of Light:

Observation Facility, Elevation: Observation Time:

Distance from Accident Site: Temperature/Dew Point:

Lowest Cloud Condition: Wind Speed/Gusts, Direction: /,

Lowest Ceiling: Visibility:

Altimeter Setting: Type of Flight Plan Filed:

Departure Point: Destination:

Wreckage and Impact Information

Crew Injuries:Aircraft Damage:SubstantialPassenger Injuries:Aircraft Fire:NoneGround Injuries:Aircraft Explosion:None

Total Injuries: Latitude, Longitude: 48.998889,2.560277 (est)

Administrative Information

| Investigator In Charge (IIC): | Bower, Daniel |
|-----------------------------------|--|
| Additional Participating Persons: | |
| Note: | The NTSB did not travel to the scene of this accident. |

Page 4 of 4 DCA19WA020