



# **Aviation Investigation Final Report**

Location: Bruington, Virginia Accident Number: GAA18CA369

Date & Time: June 20, 2018, 12:30 Local Registration: N8090X

Aircraft: Cessna 172 Aircraft Damage: Substantial

**Defining Event:** Nose over/nose down **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that, after taking off from an unimproved gravel surface in a field, he did not feel comfortable with the airplane's performance, so he chose to abort the takeoff. The airplane touched down on soft dirt, and the nose landing gear then dug into the dirt and separated from the airplane. The airplane then nosed over and came to rest inverted.

The airplane sustained substantial damage to the right wing and empennage.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper decision to abort the takeoff with insufficient runway remaining to safely stop the airplane.

# **Findings**

Personnel issues Decision making/judgment - Pilot

**Environmental issues** (general) - Decision related to condition

Aircraft (general) - Capability exceeded

**Environmental issues** Soft surface - Effect on operation

Page 2 of 5 GAA18CA369

# **Factual Information**

# **History of Flight**

Takeoff-rejected takeoff Miscellaneous/other

Landing Part(s) separation from AC

Landing Nose over/nose down (Defining event)

#### **Pilot Information**

Certificate:	Airline transport; Commercial; Flight engineer; Military	Age:	52,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	Lap only
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Without waivers/limitations	Last FAA Medical Exam:	May 17, 2018
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	April 14, 2018
Flight Time:	(Estimated) 10235 hours (Total, all aircraft), 350 hours (Total, this make and model), 2780 hours (Pilot In Command, all aircraft), 331 hours (Last 90 days, all aircraft), 89 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Page 3 of 5 GAA18CA369

# Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N8090X
Model/Series:	172 B	Aircraft Category:	Airplane
Year of Manufacture:	1961	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17248590
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	October 23, 2017 Annual	Certified Max Gross Wt.:	2250 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	2872 Hrs at time of accident	Engine Manufacturer:	CONT MOTOR
ELT:	C91 installed, not activated	Engine Model/Series:	0-300 SER
Registered Owner:		Rated Power:	145 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KXSA,135 ft msl	Distance from Accident Site:	4 Nautical Miles
Observation Time:	16:35 Local	Direction from Accident Site:	67°
<b>Lowest Cloud Condition:</b>		Visibility	10 miles
Lowest Ceiling:	Broken / 3200 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	None / None
Wind Direction:		Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	29.87 inches Hg	Temperature/Dew Point:	30°C / 23°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Bruington, VA	Type of Flight Plan Filed:	None
Destination:	Tappahannock, VA (XSA)	Type of Clearance:	None
Departure Time:	12:30 Local	Type of Airspace:	Class G

Page 4 of 5 GAA18CA369

#### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.821666,-76.969169(est)

#### **Administrative Information**

Investigator In Charge (IIC):Swenson, EricAdditional Participating Persons:Steve Harness; FAA; Richmond, VAOriginal Publish Date:March 18, 2019Note:This accident report documents the factual circumstances of this accident as described to the NTSB.Investigation Docket:https://data.ntsb.gov/Docket?ProjectID=97548

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA369