



# **Aviation Investigation Final Report**

Location: Batavia, Ohio Accident Number: GAA18CA425

Date & Time: July 13, 2018, 15:40 Local Registration: N12064

Aircraft: Cessna 172 Aircraft Damage: Substantial

**Defining Event:** Hard landing **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

#### **Analysis**

The solo student pilot reported that, during the landing flare, he pulled back on the controls too sharply and that the airplane then ballooned and landed hard. Unbeknownst to him, the propeller struck the runway, and he then went around the traffic pattern again. He landed and taxied the airplane back to the ramp without further incident.

The airplane sustained substantial damage to the firewall and lower fuselage.

The student reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

#### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The student pilot's improper landing flare, which resulted in a hard landing.

#### **Findings**

Aircraft Landing flare - Not attained/maintained

Personnel issues Aircraft control - Student/instructed pilot

Page 2 of 5 GAA18CA425

# **Factual Information**

# **History of Flight**

Landing-flare/touchdown	Miscellaneous/other
Landing-flare/touchdown	Abnormal runway contact
Landing	Hard landing (Defining event)

### **Student pilot Information**

Certificate:	Student	Age:	61,Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 22, 2018
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	205 hours (Total, all aircraft)		

# **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N12064
Model/Series:	172 S	Aircraft Category:	Airplane
Year of Manufacture:	2005	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	172S9839
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	IO-360-L2A
Registered Owner:		Rated Power:	
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA425

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KLUK,490 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	19:53 Local	Direction from Accident Site:	279°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	50°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.11 inches Hg	Temperature/Dew Point:	32°C / 17°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Batavia, OH (I69)	Type of Flight Plan Filed:	Unknown
Destination:	Batavia, OH (I69)	Type of Clearance:	Unknown
Departure Time:		Type of Airspace:	Class G

# **Airport Information**

Airport:	CLERMONT COUNTY 169	Runway Surface Type:	Asphalt
Airport Elevation:	843 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	3566 ft / 75 ft	VFR Approach/Landing:	Full stop

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.078887,-84.209724(est)

Page 4 of 5 GAA18CA425

#### **Administrative Information**

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Mike Puehler; FAA; Cincinnati, OH

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=97804">https://data.ntsb.gov/Docket?ProjectID=97804</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA18CA425