



Aviation Investigation Final Report

Location: Prescott, Washington Accident Number: GAA18CA296

Date & Time: May 16, 2018, 17:00 Local Registration: N182EW

Aircraft: Cessna 182 Aircraft Damage: Substantial

Defining Event: Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

According to the pilot, during taxi on a loose dirt surface, he initiated a left 180° turn. He reported that he was using a "fairly aggressive power setting to compensate for the surface conditions." During the left turn, the right wingtip struck the ground. Additionally, the propeller struck the ground, and the airplane then rolled left, and the left wing struck the ground.

The airplane sustained substantial damage to left wing.

The pilot reported that the accident could have been prevented if the airplane's power setting had not been more than what was needed and that "a more conservative power setting and slower taxi speed could prevent future occurrences."

The pilot reported that there were no mechanical malfunctions or failures with the airplane that would have precluded normal operation.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's taxiing too fast on rough terrain, which resulted in a loss of directional control.

Findings

Environmental issues Rough terrain - Effect on operation

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

Page 2 of 5 GAA18CA296

Factual Information

History of Flight

Taxi-into takeoff position	Collision with terr/obj (non-CFIT)
Taxi-into takeoff position	Loss of control on ground (Defining event)

Pilot Information

Certificate:PrivateAge:44,MaleAirplane Rating(s):Single-engine landSeat Occupied:LeftOther Aircraft Rating(s):NoneRestraint Used:UnknownInstrument Rating(s):NoneSecond Pilot Present:NoInstructor Rating(s):NoneToxicology Performed:NoMedical Certification:Class 3 Without waivers/limitationsLast FAA Medical Exam:October 9, 2013Occupational Pilot:NoLast Flight Review or Equivalent:December 21, 2017Flight Time:(Estimated) 283 hours (Total, all aircraft), 7 hours (Last 24 hours, all aircraft), 7 hours (Last 24 hours, all aircraft), 4 hours (Last 24 hours (Pilot In Command, all aircraft), 7 hours (Last 24 hours, all aircraft)				
Other Aircraft Rating(s):NoneRestraint Used:UnknownInstrument Rating(s):NoneSecond Pilot Present:NoInstructor Rating(s):NoneToxicology Performed:NoMedical Certification:Class 3 Without waivers/limitationsLast FAA Medical Exam:October 9, 2013Occupational Pilot:NoLast Flight Review or Equivalent:December 21, 2017Flight Time:(Estimated) 283 hours (Total, all aircraft), 39 hours (Total, this make and model), 162 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1	Certificate:	Private	Age:	44,Male
Instrument Rating(s):NoneSecond Pilot Present:NoInstructor Rating(s):NoneToxicology Performed:NoMedical Certification:Class 3 Without waivers/limitationsLast FAA Medical Exam:October 9, 2013Occupational Pilot:NoLast Flight Review or Equivalent:December 21, 2017Flight Time:(Estimated) 283 hours (Total, all aircraft), 39 hours (Total, this make and model), 162 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1	Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Instructor Rating(s): None Toxicology Performed: No Medical Certification: Class 3 Without waivers/limitations Last FAA Medical Exam: October 9, 2013 Occupational Pilot: No Last Flight Review or Equivalent: December 21, 2017 Flight Time: (Estimated) 283 hours (Total, all aircraft), 39 hours (Total, this make and model), 162 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1	Other Aircraft Rating(s):	None	Restraint Used:	Unknown
Medical Certification:Class 3 Without waivers/limitationsLast FAA Medical Exam:October 9, 2013Occupational Pilot:NoLast Flight Review or Equivalent:December 21, 2017Flight Time:(Estimated) 283 hours (Total, all aircraft), 39 hours (Total, this make and model), 162 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1	Instrument Rating(s):	None	Second Pilot Present:	No
Occupational Pilot: No Last Flight Review or Equivalent: December 21, 2017 Flight Time: (Estimated) 283 hours (Total, all aircraft), 39 hours (Total, this make and model), 162 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1	Instructor Rating(s):	None	Toxicology Performed:	No
Flight Time: (Estimated) 283 hours (Total, all aircraft), 39 hours (Total, this make and model), 162 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1	Medical Certification:	Class 3 Without waivers/limitations	Last FAA Medical Exam:	October 9, 2013
In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1	Occupational Pilot:	No	Last Flight Review or Equivalent:	December 21, 2017
	Flight Time:	In Command, all aircraft), 7 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 1		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N182EW
Model/Series:	182 P	Aircraft Category:	Airplane
Year of Manufacture:	1976	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18264841
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	May 12, 2018 Annual	Certified Max Gross Wt.:	2348 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	3440 Hrs at time of accident	Engine Manufacturer:	CONT MOTOR
ELT:	Installed, not activated	Engine Model/Series:	IO-470-F
Registered Owner:		Rated Power:	260 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA18CA296

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ALW	Distance from Accident Site:	
Observation Time:	23:53 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	180°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	29.85 inches Hg	Temperature/Dew Point:	23°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Walla Walla, WA (ALW)	Type of Flight Plan Filed:	None
Destination:	Prescott, WA	Type of Clearance:	VFR
Departure Time:	16:25 Local	Type of Airspace:	Class G

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	46.220832,-118.121948(est)

Administrative Information

Investigator In Charge (IIC):	Hicks, Michael
Additional Participating Persons:	Kevin Marsac; FAA; Spokane, WA
Original Publish Date:	March 18, 2019
Note:	This accident report documents the factual circumstances of this accident as described to the NTSB.
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=97316

Page 4 of 5 GAA18CA296

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA296