

# **Aviation Investigation Final Report**

Location: Albuquerque, New Mexico Accident Number: GAA17CA547

Date & Time: September 21, 2017, 13:00 Local Registration: N180SA

Aircraft: Cessna 180 Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot reported that, during the takeoff roll in the tailwheel-equipped airplane, with the tailwheel raised, a wind gust from the right lifted the right wing. The pilot overcorrected with right aileron control, and the right wing and horizontal stabilizer contacted the runway surface. The airplane subsequently veered off the runway to the left and came to a stop.

Postaccident examination of the airplane revealed substantial damage to the right wing and empennage.

The pilot reported that there were no preaccident mechanical malfunctions or failures with the airplane that would have precluded normal operation.

The automated weather observation system located on the airport reported that, about 13 minutes before the accident, the wind was from 220° at 10 knots, gusting to 20 knots. About 13 minutes after the accident, the wind was from 200° at 8 knots, gusting to 19 knots. The pilot landed on runway 22.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the takeoff roll in gusting crosswind conditions.

#### **Findings**

Personnel issues Aircraft control - Pilot

Aircraft Directional control - Not attained/maintained

**Environmental issues** Gusts - Effect on operation

Environmental issues Crosswind - Effect on operation

Page 2 of 5 GAA17CA547

# **Factual Information**

# **History of Flight**

Takeoff	Other weather encounter	
Takeoff	Loss of control on ground (Defining event)	
Takeoff	Runway excursion	

#### **Pilot Information**

Certificate:	Private	Age:	62,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	January 4, 2016
Occupational Pilot:	No	Last Flight Review or Equivalent:	August 24, 2016
Flight Time:	(Estimated) 648 hours (Total, all aircraft), 201 hours (Total, this make and model)		

### **Aircraft and Owner/Operator Information**

•			
Aircraft Make:	Cessna	Registration:	N180SA
Model/Series:	180 H	Aircraft Category:	Airplane
Year of Manufacture:	1968	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18051903
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	May 26, 2017 Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	5676.9 Hrs at time of accident	Engine Manufacturer:	Continental
ELT:	C91 installed, not activated	Engine Model/Series:	180H
Registered Owner:		Rated Power:	230 Horsepower
Operator:	On file	Operating Certificate(s) Held:	None

Page 3 of 5 GAA17CA547

# Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KAEG,5837 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	18:47 Local	Direction from Accident Site:	97°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots / 20 knots	Turbulence Type Forecast/Actual:	/ None
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/ N/A
Altimeter Setting:	30.04 inches Hg	Temperature/Dew Point:	27°C / 2°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	Albuquerque, NM (AEG)	Type of Flight Plan Filed:	VFR
Destination:	OKLAHOMA CITY, OK (RCE )	Type of Clearance:	VFR
Departure Time:	13:00 Local	Type of Airspace:	Class C

# **Airport Information**

Airport:	DOUBLE EAGLE II AEG	Runway Surface Type:	Asphalt
Airport Elevation:	5837 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	7398 ft / 100 ft	VFR Approach/Landing:	None

# Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	35.145557,-106.800552(est)

Page 4 of 5 GAA17CA547

#### **Administrative Information**

Investigator In Charge (IIC): Vanover, Jackie

Additional Participating Persons: Steve J Poiani; FAA; Albuquerque, NM

Original Publish Date: April 23, 2018

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=96055">https://data.ntsb.gov/Docket?ProjectID=96055</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 5 of 5 GAA17CA547