



**GAA18CA569** 

N760AC

# **Aviation Investigation Final Report**

Location: Grass Valley, Oregon Accident Number:

Date & Time: September 15, 2018, 18:00 Local Registration:

Aircraft: Maule M7 Aircraft Damage: Substantial

**Defining Event:** Loss of control on ground **Injuries:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot of the tailwheel-equipped airplane reported that, during the second approach to the unimproved canyon airstrip in moderate turbulence, he felt that the groundspeed was faster than normal and that he there was a tailwind, but he reduced power to idle and landed the airplane. About 300 ft into the ground roll, at 35 mph, the airplane veered left. He applied right rudder and moderate braking, but the airplane exited the airstrip to the left, and its left main landing gear struck a pile of rocks that were painted white and used to mark the edge of the runway. The left main landing gear separated from the airplane.

The airplane sustained substantial damage to the fuselage, left wing, and left aileron.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

An automated weather observation system about 16 nautical miles from the accident site reported that, about the time of the accident, the wind was from 290° at 13 knots, gusting to 16 knots. The pilot was landing to the south.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's failure to maintain directional control during the landing roll.

### **Findings**

Aircraft Directional control - Not attained/maintained

Personnel issues Aircraft control - Pilot

**Environmental issues** Tailwind - Effect on operation

**Environmental issues** Gusts - Effect on operation

Page 2 of 5 GAA18CA569

# **Factual Information**

## **History of Flight**

| Landing | Other weather encounter                    |
|---------|--|
| Landing | Loss of control on ground (Defining event) |
| Landing | Attempted remediation/recovery             |
| Landing | Runway excursion                           |
| Landing | Collision with terr/obj (non-CFIT)         |
| Landing | Part(s) separation from AC                 |

### **Pilot Information**

| Private  | Age:  | 45,Male   |
|--|---|---|
| Single-engine land   | Seat Occupied:  | Left  |
| None   | Restraint Used:   | Unknown   |
| None   | Second Pilot Present:   | No  |
| None   | Toxicology Performed:   | No  |
| Class 3 Without waivers/limitations  | Last FAA Medical Exam:  | September 30, 2017  |
| No   | Last Flight Review or Equivalent:   | October 10, 2016  |
| (Estimated) 1315 hours (Total, all aircraft), 1120 hours (Total, this make and model), 1315 hours (Pilot In Command, all aircraft), 59 hours (Last 90 days, all aircraft), 12 hours (Last 30 days, all aircraft) |   |   |
|  | Single-engine land  None  None  Class 3 Without waivers/limitations  No  (Estimated) 1315 hours (Total, all aird (Pilot In Command, all aircraft), 59 hours | Single-engine land  None  Restraint Used:  None  Second Pilot Present:  None  Toxicology Performed:  Class 3 Without waivers/limitations  Last FAA Medical Exam:  No  Last Flight Review or Equivalent:  (Estimated) 1315 hours (Total, all aircraft), 1120 hours (Total, this make and (Pilot In Command, all aircraft), 59 hours (Last 90 days, all aircraft), 12 hours |

Page 3 of 5 GAA18CA569

### Aircraft and Owner/Operator Information

| Aircraft Make:                | Maule                       | Registration:                     | N760AC          |
|-------------------------------|-----------------------------|-----------------------------------|-----------------|
| Model/Series:                 | M7 260C                     | Aircraft Category:                | Airplane        |
| Year of Manufacture:          | 2012                        | Amateur Built:                    |                 |
| Airworthiness Certificate:    | Normal                      | Serial Number:                    | 30052C          |
| Landing Gear Type:            | Tailwheel                   | Seats:                            | 4               |
| Date/Type of Last Inspection: | August 27, 2018 Annual      | Certified Max Gross Wt.:          | 2500 lbs        |
| Time Since Last Inspection:   |                             | Engines:                          | 1 Reciprocating |
| Airframe Total Time:          | 969 Hrs at time of accident | Engine Manufacturer:              | Lycoming        |
| ELT:                          | Installed, not activated    | Engine Model/Series:              | 10-540          |
| Registered Owner:             |                             | Rated Power:                      | 260 Horsepower  |
| Operator:                     | On file                     | Operating Certificate(s)<br>Held: | None            |

## Meteorological Information and Flight Plan

| Conditions at Accident Site:     | Visual (VMC)                     | Condition of Light:                  | Day               |
|----------------------------------|----------------------------------|--------------------------------------|-------------------|
| Observation Facility, Elevation: | KDLS,210 ft msl                  | Distance from Accident Site:         | 16 Nautical Miles |
| Observation Time:                | 00:53 Local                      | Direction from Accident Site:        | 309°              |
| <b>Lowest Cloud Condition:</b>   | Clear                            | Visibility                           | 10 miles          |
| Lowest Ceiling:                  | None                             | Visibility (RVR):                    |                   |
| Wind Speed/Gusts:                | 13 knots / 16 knots              | Turbulence Type Forecast/Actual:     | None / Unknown    |
| Wind Direction:                  | 290°                             | Turbulence Severity Forecast/Actual: | N/A / Light       |
| Altimeter Setting:               | 29.81 inches Hg                  | Temperature/Dew Point:               | 19°C / 6°C        |
| Precipitation and Obscuration:   | No Obscuration; No Precipitation |                                      |                   |
| Departure Point:                 | Hood River, OR (4S2)             | Type of Flight Plan Filed:           | None              |
| Destination:                     | Grass Valley, OR                 | Type of Clearance:                   | None              |
| Departure Time:                  | 17:30 Local                      | Type of Airspace:                    | Class G           |
|                                  |                                  |                                      |                   |

Page 4 of 5 GAA18CA569

#### **Wreckage and Impact Information**

| Crew Injuries:      | 1 None | Aircraft Damage:        | Substantial            |
|---------------------|--------|-------------------------|------------------------|
| Passenger Injuries: |        | Aircraft Fire:          | None                   |
| Ground Injuries:    | N/A    | Aircraft Explosion:     | None                   |
| Total Injuries:     | 1 None | Latitude,<br>Longitude: | 45.45,-120.863609(est) |

#### **Administrative Information**

Investigator In Charge (IIC): Swenson, Eric

Additional Participating Persons: Erik Ramseyer; FAA; Portland, OR

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to the NTSB.

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=98360

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

Page 5 of 5 GAA18CA569