



# **Aviation Investigation Final Report**

**Location:** Crystal River, Florida

August 6, 2018, 10:30 Local

Aircraft: Cessna 172

**Defining Event:** Hard landing

Flight Conducted Under: Part 91: General aviation - Personal

Accident Number: GAA18CA478

**Registration:** N9608H

Aircraft Damage: Substantial

**Injuries:** 1 None

### **Analysis**

Date & Time:

The pilot reported that the airplane landed hard, and the propeller struck the runway.

The airplane sustained substantial damage to the engine mount.

The pilot reported that there were no preaccident mechanical failures or malfunctions with the airplane that would have precluded normal operation.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

The pilot's improper landing flare, which resulted in a hard landing.

#### **Findings**

Aircraft Landing flare - Not attained/maintained

Personnel issues Aircraft control - Pilot

### **Factual Information**

### **History of Flight**

Landing	Hard landing (Defining event)
Landing	Collision with terr/obj (non-CFIT)

### **Pilot Information**

Certificate:	Private	Age:	76,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	3-point
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 With waivers/limitations	Last FAA Medical Exam:	June 7, 2017
Occupational Pilot:	No	Last Flight Review or Equivalent:	December 19, 2017
Flight Time:	(Estimated) 522 hours (Total, all aircraft), 37 hours (Total, this make and model), 368 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft)		

### **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N9608H
Model/Series:	172 M	Aircraft Category:	Airplane
Year of Manufacture:	1975	Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17266261
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-320 SERIES
Registered Owner:		Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None

Page 2 of 4 GAA18CA478

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	KCGC,10 ft msl	Distance from Accident Site:	0 Nautical Miles
Observation Time:	14:35 Local	Direction from Accident Site:	92°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	None / None
Wind Direction:	50°	Turbulence Severity Forecast/Actual:	N/A / N/A
Altimeter Setting:	30.17 inches Hg	Temperature/Dew Point:	30°C / 22°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	Crystal River, FL (CGC)	Type of Flight Plan Filed:	None
Destination:	Crystal River, FL (CGC )	Type of Clearance:	None
Departure Time:	09:00 Local	Type of Airspace:	Class G

### **Airport Information**

Airport:	CRYSTAL RIVER-CAPTAIN TOM DAVI CGC	Runway Surface Type:	Asphalt
Airport Elevation:	8 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	09	IFR Approach:	None
Runway Length/Width:	4557 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	28.867221,-82.574722(est)

Page 3 of 4 GAA18CA478

#### **Administrative Information**

Investigator In Charge (IIC): Benhoff, Kathryn

Additional Participating Persons: Camanche Cain; FAA; Tampa, FL

Original Publish Date: March 18, 2019

Note: This accident report documents the factual circumstances of this accident as described to

the NTSB.

Investigation Docket: <a href="https://data.ntsb.gov/Docket?ProjectID=98020">https://data.ntsb.gov/Docket?ProjectID=98020</a>

The National Transportation Safety Board (NTSB), established in 1967, is an independent federal agency mandated by Congress through the Independent Safety Board Act of 1974 to investigate transportation accidents, determine the probable causes of the accidents, issue safety recommendations, study transportation safety issues, and evaluate the safety effectiveness of government agencies involved in transportation. The NTSB makes public its actions and decisions through accident reports, safety studies, special investigation reports, safety recommendations, and statistical reviews.

The Independent Safety Board Act, as codified at 49 U.S.C. Section 1154(b), precludes the admission into evidence or use of any part of an NTSB report related to an incident or accident in a civil action for damages resulting from a matter mentioned in the report. A factual report that may be admissible under 49 U.S.C. § 1154(b) is available <a href="here">here</a>.

Page 4 of 4 GAA18CA478